



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	ML ML 280 CDI EDITION S
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-06-13
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-02-15
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	48
Total items failed	1

MOT #16	2021-02-16 13:29
MOT test number	699287125296
Result	✓ Passed
Next expiry date	2022-02-15
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 255/50/19 (5.2.3 (e))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #15	2021-02-16 13:25
MOT test number	857889930236
Result	✗ Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 255/50/19 (5.2.3 (e))

**MOT #14**

2020-01-27 11:22

**MOT test number**

748859407529

**Result**

✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Outer seat has child seat fitted

**Advice** Front Small chips in front windscreen driverside and passengerside

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Child seat fitted

**Advice** Front Oil level just above minimum

**MOT #13**

2020-01-20 10:06

**MOT test number**

938605960138

**Result**

✗ Failed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Outer seat has child seat fitted

**MAJOR** Nearside Rear Brake pipe excessively corroded Front to rear pipes to rear flexible hose (1.1.11 (c))

**Advice** Front Small chips in front windscreen driverside and passengerside

**MAJOR** Nearside Rear Coil spring fractured or broken Top part of spring broken (5.3.1 (b) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Child seat fitted

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Front Oil level just above minimum

**MAJOR** Offside Rear Brake pipe excessively corroded Front to rear pipe to rear flexible hose (1.1.11 (c))

**MOT #12**

2019-01-21 16:50

**MOT test number**

561915975493

**Result**

✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view Chip in front screen middle of driverside front screen (3.2 (a) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2019-01-21 16:31**MOT test number** 881474280543**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Rotational noise engine bay area**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view Small chip middle of driverside front screen (3.2 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2019-01-16 09:29**MOT test number** 709359517798**Result** ✗ Failed**MAJOR** Offside Front Brake pipe excessively corroded Pipe to flexible brake hose (1.1.11 (c))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view Small chip middle of driverside front screen (3.2 (a) (i))**MAJOR** Offside Front Brake hose excessively deteriorated Badly perished /split (1.1.12 (b) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Rotational noise engine bay area**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Front Brake hose excessively deteriorated Badly perished/ split (1.1.12 (b) (ii))**MOT #9** 2018-01-22 12:31**MOT test number** 463514586084**Result** ✓ Passed

**MOT #8** 2018-01-19 09:31**MOT test number** 249354431832**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-01-14 13:02**MOT test number** 165532947798**Result** ✓ Passed**MOT #6** 2015-10-08 11:23**MOT test number** 695407269169**Result** ✓ Passed**Advice** N/S/R SHOCK LEAKING / SLIGHT TWIST ON O/S/R FLEXI HOSE**Advice** UNDER COVERS FITTED X ENGINE / N/S/HANDBRAKE CABLE**Advice** O/S/F TYRE 2.2MM / N/S/F TYRE 2.5MM / O/S/F BRAKE PIPE CORRODING**MOT #5** 2014-10-06 16:10**MOT test number** 498409474281**Result** ✓ Passed**Notice** CORROSION ON O/S/F BRAKE PIPE / N/S/R TYRE 2.8MM / DAMAGE TO N/S HANDBRAKE / O/S/R PADS GETTING LOW**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2013-10-15 16:08**MOT test number** 956648783251**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** O/S/F BRAKE PIPE CORRODING /. N/S HANDBRAKE OUTER CASING IN POOR COND
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2012-10-18 15:09**MOT test number** 718332492258**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2011-10-20 09:00**MOT test number** 107133991224**Result** ✓ Passed**MOT #1** 2010-12-06 10:05**MOT test number** 470450740317**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



## Tax &amp; MOT check

×

**Untaxed**

**Tax expired:**  
1 July 2022

×

**MOT**

**Expired:**  
15 February 2022

## Tax status

Expired at 1 July 2022

## Days left

669 days too late

## MOT expiry date

15 February 2022

## Full MOT history

[See MOT history](#)

## Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-






Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-11-23
Last registration	2021-02-16
Complete history	<a href="#">See info</a>



Registration #1	2007-11-23	12 mi
Registration #2	2010-12-06	38.320 mi
Registration #3	2011-10-20	46.343 mi
Registration #4	2012-10-18	55.191 mi
Registration #5	2013-10-15	87.359 mi
Registration #6	2014-10-06	115.987 mi
Registration #7	2015-10-08	145.899 mi
Registration #8	2017-01-14	151.139 mi
Registration #9	2019-05-20	25,277 (max)
Registration #10	2019-05-20	25,277 (max)
Registration #11	2019-05-20	25,277 (max)
Registration #12	2019-05-20	25,277 (max)
Registration #13	2019-05-20	25,277 (max)
Registration #14	2019-05-20	25,277 (max)
Registration #15	2019-05-20	25,277 (max)
Registration #16	2019-05-20	25,277 (max)

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040371305