





report date: 2024-03-29

General information

Make	MINI	
Model	JOHN COOPER WORKS COOPER S	
Colour	Silver	
Year of manufacture	2017	
Top speed	143 mph	
0 - 60 mph	6.8 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	192 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2023-08-10

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2023-08-03
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT h	nistory
-------	---------

MOT expiry date	2024-08-15
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #7	2023-08-16 14:23
MOT test number	946555963282
Result	✓ Passed
Next expiry date	2024-08-15

MOT #6		2023-05-23 11:48
MOT te	st number	952364013087
Result		✓ Passed
Advic	Items removed from driver's view prior to test	
Advic	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #5		2023-05-23 11:48
MOT test number		667903535394
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Items removed f	rom driver's view prior to test	

MOT #4	2022-05-20 13:04
MOT test number	114544908411
Result	√ Passed

CarCheck.co.uk page 3/11



MOT #3 2022-05-20 07:57

MOT test number 793003153179

Result X Failed

Fail Offside Front Outer Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing both perishing 2016 DOM (5.2.3 (d) (ii))

Pass with rectification Front Headlamp aim too low BOTH (4.1.2 (a))

Advice Front Tyre slightly damaged/cracking or perishing both perishing 2016 DOM (5.2.3 (d) (ii))

Advice Front Items removed from driver's view prior to test

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords advise replacing (5.2.3 (d) (i))

MOT #2 2021-05-18 08:52

MOT test number 659160727214

Result

Passed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2020-12-04 13:58

MOT test number 125729466943

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



\sim		100	
Owi	ner	nıs	torv

,		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
2000000		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

page 8/11 CarCheck.co.uk



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-12-29
Last registration	2023-08-16
Complete history	See info



Registration #1	2017-12-29	13 mi
Registration #2	2020-12-04	15.348 mi
Registration #3		11.777 es
Registration #4	2021-05-18	16.025 mi
Registration #5	2022-05-20	26.332 mi
Registration #6	2022-05-20	26.334 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1425 mm
Length	3982 mm
Wheel base	2567 mm
Kerb weight	1315 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	44	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1:	1/11