



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Blue
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-05-14
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-15
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	9

MOT #10	2024-03-15 16:17
MOT test number	675017805980
Result	✓ Passed
Next expiry date	2025-03-15
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2024-03-11 13:44
MOT test number	930393928266
Result	✗ Failed
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened PROMPT REPLACEMENT ADVISED (1.1.14 (a) (ii))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #8** 2023-03-08 14:09**MOT test number** 176020395890**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2022-03-14 15:01**MOT test number** 460456982215**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2022-03-14 09:42**MOT test number** 649375839464**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2021-03-15 11:54**MOT test number** 739629474632**Result** ✓ Passed**MOT #4** 2021-03-12 15:14**MOT test number** 831098388891**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))



MOT #3	2020-03-13 12:17
MOT test number	566151565376
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2019-03-14 10:14
MOT test number	616792867046
Result	✓ Passed

MOT #1	2018-03-12 12:01
MOT test number	185049962583
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-16
Last registration	2024-03-15
Complete history	See info



Registration #1	2015-03-16	9 mi
Registration #2	2018-03-12	31.923 mi
Registration #3	2019-03-14	38.401 mi
Registration #4	2020-03-13	46.369 mi
Registration #5	2021-03-12	50.820 mi
Registration #6	2021-03-15	50.820 mi
Registration #7	2022-03-15	50.820 mi
Registration #8	2023-03-15	50.820 mi
Registration #9	2024-03-15	50.820 mi
Registration #10	2024-03-15	50.820 mi
Registration #11	2024-03-15	50.820 mi
Registration #12	2024-03-15	50.820 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDFZ359220