



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | HYUNDAI |
| Model | GETZ CRTD GSI |
| Colour | Red |
| Year of manufacture | 2008 |
| Top speed | 107 mph |
| 0 - 60 mph | 16.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 81 BHP |
| Max. torque | 191 Nm at 2.500 rpm |
| Engine capacity | 1.493 cc |
| Cylinders | 3 |
| Fuel type | Diesel |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 118 g/km |
| CO2 label | C |






Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-10-31 |
| Pictures | 32 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-17 |
| Pictures | 32 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-31 |
| MOT pass rate | 64 % |
| MOT passed | 14 |
| Failed MOT tests | 8 |
| Total advice items | 24 |
| Total items failed | 16 |

| | |
|------------------|---|
| MOT #22 | 2023-10-30 15:31 |
| MOT test number | 804897325734 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-31 |
| Advice | Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i)) |

| | |
|-----------------|---|
| MOT #21 | 2023-10-30 12:05 |
| MOT test number | 795039055647 |
| Result | ✗ Failed |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| Advice | Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i)) |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Fail | Nearside Front Macpherson strut likely to become detached (5.3.3 (a) (ii)) |
| Fail | Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) |
| Fail | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |
| Fail | Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) |

**MOT #20** 2022-10-24 11:05**MOT test number** 588680274268**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #19** 2022-10-24 09:56**MOT test number** 789248444554**Result** ✗ Failed**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #18** 2021-11-01 10:43**MOT test number** 432410048981**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2021-10-29 12:21**MOT test number** 361484122665**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #16**

2020-11-27 15:19

MOT test number

764397483937

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #15**

2020-11-27 11:01

MOT test number

879993243727

Result

✗ Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Headlamp aim too high (4.1.2 (a))**MOT #14**

2019-11-25 14:21

MOT test number

395082556012

Result

✓ Passed

Advice Front Subframe mounting prescribed area is corroded but not considered excessive offside and nearside (5.3.6 (a) (i))**Advice** Sub-frame corroded but not seriously weakened front and rear (5.3.3 (b) (i))**Advice** Front Lower Suspension arm corroded but not seriously weakened offside and nearside (5.3.3 (b) (i))

**MOT #13** 2018-12-17 11:17**MOT test number** 636679783290**Result** ✓ Passed**MOT #12** 2018-12-17 11:17**MOT test number** 721678724709**Result** ✗ Failed**Pass with rectification** Central Front Position lamp not working (4.2.1 (a))**MOT #11** 2017-12-16 09:34**MOT test number** 801872871066**Result** ✓ Passed**MOT #10** 2017-12-16 09:34**MOT test number** 553209931281**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**MOT #9** 2016-12-20 13:47**MOT test number** 799227517315**Result** ✓ Passed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #8** 2016-12-19 16:37**MOT test number** 876892521978**Result** ✗ Failed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)



| | |
|---------------|------------------|
| MOT #7 | 2016-01-30 10:22 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 974332566799 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #6 | 2015-01-31 10:43 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 648771635038 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2014-02-01 08:47 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 886172634001 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|-----------------------|
| Notice | Rear brake discs poor |
|---------------|-----------------------|

| | |
|---------------|------------------|
| MOT #4 | 2013-02-02 08:27 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 409533133074 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2012-02-14 08:44 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 437415942065 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2011-02-26 16:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 529797251058 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



| | |
|-----------------|--|
| MOT #1 | 2011-02-26 09:50 |
| MOT test number | 198197451418 |
| Result | ✗ Failed |
| Fail | Nearside rear brake binding (3.7.B.1) |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) |
| Fail | Offside rear brake binding (3.7.B.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
31 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 31 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | KM08CKL |
| Plate since | 2019-09-28 |
| Current registration | KM08CKL |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 25 |
| First mileage registration | 2008-03-28 |
| Last registration | 2023-10-30 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-03-28 | 26 mi |
| Registration #2 | 2011-02-26 | 19.016 mi |
| Registration #3 | 2011-02-26 | 19.016 mi |
| Registration #4 | 2012-02-14 | 24.459 mi |
| Registration #5 | 2013-02-02 | 29.505 mi |
| Registration #6 | 2014-02-01 | 34.767 mi |
| Registration #7 | 2015-01-31 | 38.931 mi |
| Registration #8 | 2016-01-30 | 43.657 mi |
| Registration #9 | 2016-12-19 | 47.338 mi |
| Registration #10 | 2016-12-20 | 47.338 mi |
| Registration #11 | 2017-12-16 | 51.282 mi |
| Registration #12 | 2017-12-16 | 51.282 mi |
| Registration #13 | 2018-12-17 | 54.797 mi |
| Registration #14 | 2019-01-29 | 55,337 mi |
| Registration #15 | 2019-01-29 | 55,337 mi |
| Registration #16 | 2019-01-29 | 55,337 mi |
| Registration #17 | 2019-01-29 | 55,337 mi |
| Registration #18 | 2019-01-29 | 55,337 mi |
| Registration #19 | 2019-01-29 | 55,337 mi |
| Registration #20 | 2019-01-29 | 55,337 mi |
| Registration #21 | 2019-01-29 | 55,337 mi |
| Registration #22 | 2019-01-29 | 55,337 mi |
| Registration #23 | 2019-01-29 | 55,337 mi |
| Registration #24 | 2019-01-29 | 55,337 mi |
| Registration #25 | 2019-01-29 | 55,337 mi |



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1665 mm |
| Height | 1500 mm |
| Length | 3810 mm |
| Wheel base | 2455 mm |
| Kerb weight | 1204 kg |
| Max. allowed weight | 1600 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FA8U514149 |