



report date: 2024-03-29

General information

Make	JAGUAR
Model	F-TYPE V6 S
Colour	Red
Year of manufacture	2013
Top speed	171 mph
0 - 60 mph	4.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	380 BHP
Max. torque	460 Nm at 3.500 rpm
Engine capacity	2.995 cc
Cylinders	6
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.0 mpg
CO2 emission	213 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-27
Pictures	56
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	3
MOT #12	2023-10-18 13:32
MOT test number	162827700902
Result	✓ Passed
Next expiry date	2024-10-19
MOT #11	2022-10-17 08:50
MOT test number	779919529891
Result	✓ Passed
MOT #10	2021-10-20 12:07
MOT test number	617549634586
Result	✓ Passed
MOT #9	2021-07-28 11:35
MOT test number	659746216958
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2021-07-26 11:15

**MOT test number**

554905834843

**Result**

✗ Failed

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Nail in tyre

**MAJOR** Offside Windscreen wiper blade missing (3.4 (b) (ii))

**MAJOR** Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Nearside Front Upper Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #7**

2020-10-02 10:39

**MOT test number**

755391073653

**Result**

✓ Passed

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Front Windscreen wiper blade defective split (3.4 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2019-10-02 09:45

**MOT test number**

860292749616

**Result**

✓ Passed

**Advice** Rear tyre/s getting low on treads

**Advice** Front tyres inner edges severely worn! Recommend attention ASAP

**MOT #5** 2018-10-17 07:12**MOT test number** 297112700362**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front tyres inner edges worn**MOT #4** 2017-10-28 10:46**MOT test number** 269101958575**Result** ✓ Passed**Advice** Both rear tyres are on the legal limit**MOT #3** 2017-10-21 13:19**MOT test number** 823383726309**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Both rear tyres are on the legal limit**MOT #2** 2016-09-15 14:24**MOT test number** 869493690648**Result** ✓ Passed**MOT #1** 2016-08-30 08:38**MOT test number** 192444243320**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
19 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	19 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-01
Last registration	2023-10-18
Complete history	<a href="#">See info</a>



Registration #1	2013-09-01	24 mi
Registration #2	2016-08-30	13.195 mi
Registration #3	2016-09-15	13.200 mi
Registration #4	2017-10-21	18.758 mi
Registration #5	2017-10-28	18.760 mi
Registration #6	2018-10-17	36.181 mi
Registration #7	2019-10-02	40.713 mi
Registration #8	2019-10-02	40.713 mi
Registration #9	2019-10-02	40.713 mi
Registration #10	2019-10-02	40.713 mi
Registration #11	2019-10-02	40.713 mi
Registration #12	2019-10-02	40.713 mi
Registration #13	2019-10-02	40.713 mi
Registration #14	2019-10-02	40.713 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1923 mm
Height	1308 mm
Length	4470 mm
Wheel base	2622 mm
Kerb weight	1614 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	13060204070306PS