





General information

| Make | RENAULT |
|---------------------|----------------------------|
| Model | KADJAR DYNAMIQUE S NAV TCE |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 121 mph |
| 0 - 60 mph | 9.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 138 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.600 rpm |
| Engine capacity | 1.330 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 2.8 mpg |
| CO2 emission | 135 g/km |
| CO2 label | E |





Internet history

Entry 1

Date

Pictures

2021-06-05

6

Listing price

View report









source: yesauto.com

ult Approved



MOT history

| | 2024.06.12 |
|--------------------|------------|
| MOT expiry date | 2024-06-12 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 13 |
| Total items failed | 1 |

| MOT #4 | | 2023-06-13 14:21 |
|----------|---|---------------------|
| MOT test | number | 590669134623 |
| Result | | ✓ Passed |
| Next exp | iry date | 2024-06-12 |
| Minor | Offside Front Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing inner/outer (5.2.3 (| d) (ii)) |
| Minor | Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) | |
| Minor | Nearside Rear Rear fog lamp lens defective which has no effect on emitted lig | ıht (4.5.1 (b) (i)) |
| Advice | Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) | |



BN68EEW report date: 2024-03-28

| MOT #3 | | 2023-06-08 11:54 |
|---------------|--|------------------|
| MOT test | number | 962815122912 |
| Result | | 🗙 Failed |
| Fail F | ront Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii)) | |
| Advice | Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing inner/outer (5.2.3 (d) (i | ii)) |
| Minor | Offside Front Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) | |
| Minor | Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Minor | Nearside Rear Rear fog lamp lens defective which has no effect on emitted light (| (4.5.1 (b) (i)) |

| MOT #2 | 2022-06-06 15:46 |
|-----------------|------------------|
| MOT test number | 288951066702 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-06-09 11:39 |
| MOT test number | 614947072370 |

Result

🗸 Passed



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|-------------------------|--------------------------|
| Tax due: 1 June 2024 | Expires: 12 June 2024 |
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 12 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FERM |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ana | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Rule sizes | |
| | |





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



BN68EEW report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-09-17 |
| Last registration | 2023-06-13 |
| Complete history | See info |



| Registration #1 | 2018-09-17 | 6 mi |
|-----------------|------------|------------|
| Registration #2 | | 11.777 est |
| Registration #3 | 2021-06-09 | 22.290 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.777 est |



BN68EEW report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 81% |
| Pedestrian | 74% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1836 mm |
| Height | 1607 mm |
| Length | 4449 mm |
| Wheel base | 2646 mm |
| Kerb weight | 1332 kg |
| Max. allowed weight | 1880 kg |
| Additional information | |
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | D006064 |