





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI DSG
Colour	Black
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

### Engine & fuel consumption

Power	140 BHP	
Max. torque	320 Nm at 2.500 rpm	
Engine capacity	1.968 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	36.2 mpg	
Consumption extra urban	56.5 mpg	
Consumption combined	47.1 mpg	
CO2 emission	158 g/km	
CO2 label	G	



CarCheck.co.uk page 1/13



# Internet history

### Entry 2

Date 2021-08-12

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



**X** Failed

MOT history

Result

MOT expiry date	2024-04-16
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	12
Total items failed	23

MOT #16	2023-04-17 12:58
MOT test number	445868524093
Result	✓ Passed
Next expiry date	2024-04-16

MOT #15	2022-03-23 11:59
MOT test number	936698095674
Result	<b>✓</b> Passed

MOT #14	2021-04-13 10:27
MOT test number	795589372214
Result	<b>✓</b> Passed

MOT #13	2021-04-12 09:17

MOT test number 294038210896

**Fail** Offside Rear Lower Suspension arm corroded and seriously weakened marked with yellow chalk (5.3.3 (b) (i))

MOT #12		2019-05-06 14:48
MOT test	number	580760307600
Result		✓ Passed
Advice	Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))	

CarCheck.co.uk page 3/13



**MOT #11** 2019-05-06 10:55

**MOT test number** 781261956076

Result X Failed

**Advice** Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))

**Fail** Reversing lamp does not emit a steady white light (4.6.2 (a))

**Fail** Nearside Rear Position lamp not working (4.2.1 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #10 2018-05-08 13:26

MOT test number 462696927919

Result \( \sqrt{Passed} \)

MOT #9 2018-04-28 10:26

MOT test number 785586680294

Result × Failed

Fail Offside Front Air suspension levelling valve insecure (2.4.D.4)

**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Rear Stop lamp not working (1.2.1b)

**Fail** Nearside Front Air suspension levelling valve insecure (2.4.D.4)

**Fail** Nearside Front coil spring broken (2.4.C.1a)

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 4/13



MOT #8

MOT test number

Passed

Advice Engine management light on

MOT #7 2017-04-27 08:53 193507236785 **MOT** test number Result **X** Failed **Advice** Engine management light on Offside Headlamp not working on dipped beam (1.7.5a) Fail Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4) Offside Rear coil spring broken (2.4.C.1a) Fail Fail Nearside Headlamp not working on dipped beam (1.7.5a) Fail Nearside Front Direction indicator not working (1.4.A.2c) Fail Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g) Rear brake application uneven (3.7.B.2) Fail

MOT #6		2016-04-05 15:29
MOT test	number	332133930366
Result		✓ Passed
Advice	Child seat fitted limiting inspection of adult seatbelt	
Advice	Offside Rear shock absorber bump stop perished	
	p approximately and the second	
Advice	Nearside Rear shock absorber bump stop perished	

CarCheck.co.uk page 5/13



**MOT #5** 2016-04-05 11:41 161993671955 **MOT** test number Result × Failed Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Nearside Rear shock absorber bump stop perished **Advice Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4) Advice Child seat fitted limiting inspection of adult seatbelt **Advice** Offside Rear shock absorber bump stop perished

 MOT #4
 2015-03-27 15:43

 MOT test number
 729426985006

 Result
 ✓ Passed

MOT #3

MOT test number

785986285091

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2014-02-14 15:14
MOT test number 335415644083

Result ✓ Passed

MOT #1

MOT test number

747155763092

Result

Notice Nearside front tyre has small cuts in sidewall

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13





# Tax & MOT check



Tax expired: 10 December 2023

# X MOT

Expired: 16 April 2024

Tax status	Expired at 10 December 2023
Days left	140 days too late
MOT expiry date	16 April 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13




### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

Owner matory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-01
Last registration	2023-04-17
Complete history	See info



Registration #1	2010-03-01	23 mi
Registration #2	2013-03-06	34.924 mi
Registration #3	2014-02-14	42.065 mi
Registration #4	2015-03-27	58.688 mi
Registration #5	2015-03-27	58.688 mi
Registration #6	2016-04-05	74.918 mi
Registration #7	2016-04-05	74.918 mi
Registration #8	2017-04-27	90.025 mi
Registration #9	2017-04-27	90.025 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1476 kg
Max. allowed weight	2110 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/12

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	CBA 755957