



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S
Colour	Blue
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-02
Pictures	41
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-24
MOT pass rate	60 %
MOT passed	15
Failed MOT tests	10
Total advice items	23
Total items failed	14

MOT #25	2023-09-25 07:10
MOT test number	741850119789
Result	✓ Passed
Next expiry date	2024-09-24

MOT #24	2023-09-20 13:01
MOT test number	797870698506
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #23	2022-08-11 13:58
MOT test number	704543430868
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #22**

2022-08-11 13:58

**MOT test number**

353521825772

**Result****✗ Failed**

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2021-08-18 09:48

**MOT test number**

671831521747

**Result****✓ Passed****MOT #20**

2021-08-18 09:48

**MOT test number**

915669852764

**Result****✗ Failed**

**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #19**

2021-04-13 11:23

**MOT test number**

566276716811

**Result****✓ Passed**

**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**MOT #18**

2021-04-13 11:23

**MOT test number**

351397193443

**Result****✗ Failed**

**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**MOT #17** 2019-05-31 15:39**MOT test number** 251340260818**Result** ✓ Passed**MOT #16** 2019-05-31 13:29**MOT test number** 955802657999**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Tyre slightly damaged/cracking or perishing Both front (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2018-05-11 13:45**MOT test number** 781433656661**Result** ✓ Passed**MOT #14** 2018-05-11 11:15**MOT test number** 258974595970**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Tyre worn close to the legal limit worn on outer edge (4.1.E.1)**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit worn on outer edge (4.1.E.1)

**MOT #13** 2017-05-31 10:25**MOT test number** 408980413276**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2017-05-31 10:25**MOT test number** 942699003853**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-05-06 08:51**MOT test number** 795246851465**Result** ✓ Passed**MOT #10** 2016-05-06 08:51**MOT test number** 467624180369**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #9** 2015-04-07 12:57**MOT test number** 156217095415**Result** ✓ Passed**MOT #8** 2014-04-08 11:58**MOT test number** 339158694044**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2013-04-05 10:44**MOT test number** 277175193086**Result** ✓ Passed**Notice** Exhaust rear box bracket deteriorated**MOT #6** 2012-03-28 14:48**MOT test number** 867508982074**Result** ✓ Passed**Notice** Rear exhaust bracket corroded**MOT #5** 2011-03-30 13:51**MOT test number** 536409281093**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2010-03-22 17:44**MOT test number** 154591480438**Result** ✓ Passed**MOT #3** 2010-03-22 11:44**MOT test number** 781571380019**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2009-03-24 14:40**MOT test number** 871373489091**Result** ✓ Passed



MOT #1	2009-03-23 14:39
MOT test number	460342689077
Result	✗ Failed
Fail	Rear Stop lamp not working (1.2.1b)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
24 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	24 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 <b>KY06LMJ</b>
Plate since	2019-06-28
Current registration	 <b>KY06LMJ</b>
Plate since	2019-06-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2006-03-21
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2006-03-21	11 mi
Registration #2	2009-03-23	22.042 mi
Registration #3	2009-03-24	22.042 mi
Registration #4	2010-03-22	27.817 mi
Registration #5	2010-03-22	27.817 mi
Registration #6	2011-03-30	34.839 mi
Registration #7	2012-03-28	41.292 mi
Registration #8	2013-04-05	46.938 mi
Registration #9	2014-04-08	53.144 mi
Registration #10	2015-04-07	57.917 mi
Registration #11	2016-05-06	61.842 mi
Registration #12	2016-05-06	61.842 mi
Registration #13	2017-05-31	65.884 mi
Registration #14	2017-05-31	65.884 mi
Registration #15	2018-05-31	65.884 mi
Registration #16	2018-05-31	65.884 mi
Registration #17	2018-05-31	65.884 mi
Registration #18	2018-05-31	65.884 mi
Registration #19	2018-05-31	65.884 mi
Registration #20	2018-05-31	65.884 mi
Registration #21	2018-05-31	65.884 mi
Registration #22	2018-05-31	65.884 mi
Registration #23	2018-05-31	65.884 mi
Registration #24	2018-05-31	65.884 mi
Registration #25	2018-05-31	65.884 mi
Registration #26	2018-05-31	65.884 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	FX6N2815197