



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-07-26
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-18
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #20	2022-08-11 08:26
MOT test number	858759624817
Result	✓ Passed
Next expiry date	2023-08-10

MOT #19	2021-09-21 09:32
MOT test number	968360961499
Result	✓ Passed
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))

MOT #18	2020-10-24 11:13
MOT test number	952551584862
Result	✓ Passed
Advice	Play in steering rack inner joint(s)
Advice	Rear Exhaust silencer slightly loose weld deteriorated (8.1.1 (b) (i))

**MOT #17**

2020-10-16 08:17

MOT test number

537507302356

Result**✗ Failed****MAJOR** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MAJOR** Horn not working (7.7 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Play in steering rack inner joint(s)**MAJOR** Offside Front Direction indicator incorrect colour (4.4.3 (a))**DANGEROUS** Brake load sensing valve inoperative and ABS not fitted or inoperative (1.1.17 (c) (ii))**Advice** Rear Exhaust silencer slightly loose weld deteriorated (8.1.1 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #16**

2019-04-18 10:20

MOT test number

286285984099

Result**✓ Passed****Advice** Offside Front anti roll bar boot slight deteriorated..**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Front anti roll bar boot slight deteriorated**Advice** Fuel tank securing straps corroded slightly..

**MOT #15** 2019-04-18 09:47**MOT test number** 144650595195**Result** ✗ Failed**Advice** Offside Front anti roll bar boot slight deteriorated..**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 175/65/14 (5.2.3 (d) (i))**Advice** Nearside Front anti roll bar boot slight deteriorated**Advice** Fuel tank securing straps corroded slightly..**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #14** 2018-03-19 12:21**MOT test number** 836615846737**Result** ✓ Passed**Advice** Fuel tank strap corroded slightly..**Advice** O/s/r tyre cracked and perished slightly..**MOT #13** 2017-03-24 14:20**MOT test number** 344024173772**Result** ✓ Passed**Advice** Fuel tank strap very rusty**MOT #12** 2016-03-24 10:51**MOT test number** 391870090023**Result** ✓ Passed**MOT #11** 2015-04-16 10:55**MOT test number** 335526505112**Result** ✓ Passed

**MOT #10** 2014-03-28 12:04**MOT test number** 178647984011**Result** ✓ Passed**Advice** Offside Front position lamp(s) slightly discoloured (1.1.A.3e)**Advice** Nearside Front position lamp(s) slightly discoloured (1.1.A.3e)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-03-26 10:53**MOT test number** 528825183026**Result** ✓ Passed**MOT #8** 2013-03-26 10:53**MOT test number** 388185183058**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2012-04-18 10:21**MOT test number** 297709402491**Result** ✓ Passed**MOT #6** 2012-04-16 16:19**MOT test number** 486447202137**Result** ✗ Failed**Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Brake load sensing valve linkage seized (3.6.E.3)

**MOT #5** 2011-03-26 11:00**MOT test number** 669925981043**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #4** 2011-03-26 11:00**MOT test number** 717835381089**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-03-26 15:04**MOT test number** 294265680066**Result** ✓ Passed**MOT #2** 2009-03-12 13:19**MOT test number** 942451879078**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2008-01-26 09:32**MOT test number** 221436028066**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KW54BRF
Plate since	2019-03-29
Current registration	KW54BRF
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-01-31
Last registration	2022-08-11
Complete history	See info



Registration #1	2005-01-31	8 mi
Registration #2	2008-01-26	13.612 mi
Registration #3	2009-03-12	22.424 mi
Registration #4	2010-03-26	29.803 mi
Registration #5	2011-03-26	39.933 mi
Registration #6	2012-04-16	46.685 mi
Registration #7	2012-04-18	46.697 mi
Registration #8	2013-03-26	50.178 mi
Registration #9	2014-03-28	54.285 mi
Registration #10	2015-04-16	59.432 mi
Registration #11	2016-03-24	63.542 mi
Registration #12	2016-03-24	63.542 mi
Registration #13	2016-03-24	63.542 mi
Registration #14	2016-03-24	63.542 mi
Registration #15	2016-03-24	63.542 mi
Registration #16	2016-03-24	63.542 mi
Registration #17	2016-03-24	63.542 mi
Registration #18	2016-03-24	63.542 mi
Registration #19	2016-03-24	63.542 mi
Registration #20	2016-03-24	63.542 mi
Registration #21	2016-03-24	63.542 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FSR95191649