





General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	Blue
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С







Internet history

Entry 1

Date Pictures 2022-08-07

23

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-06
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	12
Total items failed	1

MOT #12	2023-07-06 08:06
MOT test number	911715812407
Result	✓ Passed
Next expiry date	2024-07-06

MOT #11	2023-06-26 10:35
MOT test	number 110720005897
Result	× Failed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords

(5.2.3 (d) (i))

MOT #10		2022-06-24 11:31
MOT test	number	999215179730
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #9	2021-07-03 11:05
MOT test number	760673103942
Result	✓ Passed





MOT #8		2021-07-03 11:05
MOT test number		912871081490
Result		🗙 Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
MOT #7		2020-07-07 09:31
MOT test number		846806029953
Result		Passed
Advice Nearside Rear Chil	ld Seat fitted not allowing full inspection of adult belt	

Advice Offside Front Nail in tyre

МОТ #6	2019-06-29 09:59
MOT test number	254826439373
Result	✓ Passed

MOT #5	2018-07-13 12:36
MOT test number	728031519949
Result	✓ Passed

MOT #4	2017-07-10 08:12
MOT test number	231400510428
Result	✓ Passed
Advice Rear Child Seat fitted not allowing full inspection of adult belt	





МОТ #3	2016-07-15 13:38
MOT test number	901086276274
Result	✓ Passed
Advice Offside Rear child seat fitted not allowing full inspection of seat belt	
Advice Has small chips in windscreen outside swept area	
Advice Nearside Rear small cut to cords in tyre	
MOT #2	2015-07-14 12:59
MOT test number	278955695466
Result	✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2014-10-22 09:07
MOT test number	378815494249
Result	✓ Passed
Advice Windscreen has damage to an area less than a	40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 6 July 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			95
MOT expiry date			6 July 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-16
Last registration	2023-07-06
Complete history	<u>See info</u>



Registration #1	2012-07-16	22 mi
Registration #2	2014-10-22	21.396 mi
Registration #3	2015-07-14	32.886 mi
Registration #4	2016-07-15	44.102 mi
Registration #5	2017-07-10	54.757 mi
Registration #6	2018-07-13	68.077 mi
Registration #7	2019-06-29	81.769 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.317 esi





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1820 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	74478198