





report date: 2024-03-28

#### General information

Make	BMW
Model	435 435D XDRIVE M SPORT GRAN COUPE
Colour	Blue
Year of manufacture	2017
Top speed	155 mph
0 - 60 mph	4.8 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/11



## Internet history

## Entry 3

Date 2023-04-07

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2023-03-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-14	
Pictures	0	
Listing price	<u>View report</u>	

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-04-12
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #6		2024-04-13 10:51
MOT test	number	406862885850
Result		🗙 Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #5	2023-04-13 16:08
MOT test number	336517234536
Result	✓ Passed

Result	✓ Passed
MOT #4	2023-04-06 06:45
MOT test	<b>number</b> 491588825583
Result	<b>★</b> Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
(5.2.3 (d)	(i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>MAJOR</b> (5.2.3 (d)	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (i))

CarCheck.co.uk page 3/11



MOT #3 2022-10-29 12:14

**MOT test number** 566532462450

MOT #2 2021-11-04 09:45

**MOT test number** 652851071201

Result 

✓ Passed

MOT #1 2020-12-16 15:22

**MOT test number** 569424770282

**Result** ✓ Passed

Advice Offside Front Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Rear Nail in tyre

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	12 April 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report h		ve?
***************************************		
THE STATE OF THE S		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-10-06
Last registration	2024-04-13
Complete history	See info



Registration #1	2017-10-06	23 mi
Registration #2	2020-12-16	26.703 mi
Registration #3		11.777 es
Registration #4	2021-11-04	33.603 mi
Registration #5	2022-10-29	43.213 mi
Devictor #6		
Registration #6		0.00
Registration #7		1.77 4
-		1.77 m
Registration #7		1.77 m

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1825 mm
Height	1412 mm
Length	4640 mm
Wheel base	2810 mm
Kerb weight	1685 kg
Max. allowed weight	2260 kg

# Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/

Number of axles2Engine number51219943