



RENAULT



DS05TPZ


report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC AUTHENTIQUE 16V G/SCENIC
Colour	Red
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-15
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	23
Total items failed	18

MOT #24 2023-07-19 09:00

MOT test number 108059676565

Result ✓ Passed

Next expiry date 2024-07-18

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Play in steering rack inner joint(s)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #23 2023-07-18 15:49

MOT test number 733618933566

Result ✗ Failed

Advice Front Play in steering rack inner joint(s)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Electronic parking brake warning indicates a malfunction (1.1.6 (e))

MOT #22 2022-07-19 12:10

MOT test number 377213775710

Result ✓ Passed

**MOT #21** 2021-09-27 13:32**MOT test number** 140929003512**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #20** 2021-09-14 10:58**MOT test number** 884382283200**Result** ✗ Failed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #19** 2020-09-09 14:54**MOT test number** 981385473389**Result** ✓ Passed**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))**MOT #18** 2019-09-02 15:02**MOT test number** 838565530643**Result** ✓ Passed**MOT #17** 2018-09-06 13:56**MOT test number** 899079997870**Result** ✓ Passed

**MOT #16** 2018-08-31 14:28**MOT test number** 372401252228**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #15** 2017-09-07 13:45**MOT test number** 751697307757**Result** ✓ Passed**MOT #14** 2017-08-25 11:27**MOT test number** 190779168709**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Electronic parking brake control defective so that it cannot be satisfactorily operated
CABLE SEIZED (3.1.3c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**Fail** Direction indicator incorrect colour BOTH REAR (1.4.A.2f)**MOT #13** 2016-08-05 13:59**MOT test number** 455100075458**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2015-07-28 14:57**MOT test number** 608029805297**Result** ✓ Passed

**MOT #11** 2015-07-28 10:48**MOT test number** 387629905214**Result** ✗ Failed**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #10** 2014-08-26 15:38**MOT test number** 847228634244**Result** ✓ Passed**MOT #9** 2014-08-19 16:54**MOT test number** 775861634267**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2013-08-19 14:41**MOT test number** 389881133295**Result** ✓ Passed**MOT #7** 2013-08-17 13:09**MOT test number** 775829423265**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Offside Stop lamp not working (1.2.1b)

**MOT #6** 2012-08-23 13:20**MOT test number** 199256132226**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-08-23 11:32**MOT test number** 346836332497**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-06-27 14:38**MOT test number** 856978071153**Result** ✓ Passed**MOT #3** 2010-06-24 14:41**MOT test number** 982665370158**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-06-20 09:52**MOT test number** 383931079153**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #1	2008-07-01 16:14
MOT test number	120363388192
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-05-29
Current registration	
Plate since	2019-05-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-08-15
Last registration	2023-07-19
Complete history	See info



Registration #1	2005-08-15	13 mi
Registration #2	2008-07-01	12.394 mi
Registration #3	2009-06-20	18.909 mi
Registration #4	2010-06-24	20.084 mi
Registration #5	2011-06-27	28.281 mi
Registration #6	2012-08-23	36.111 mi
Registration #7	2012-08-23	36.111 mi
Registration #8	2013-08-17	41.227 mi
Registration #9	2013-08-19	41.295 mi
Registration #10	2014-08-19	45.709 mi
Registration #11	2014-08-26	45.779 mi
Registration #12	2015-07-28	49.364 mi
Registration #13	2015-07-28	49.366 mi
Registration #14	2015-08-20	51.377 mi
Registration #15	2015-08-20	51.377 mi
Registration #16	2015-08-20	51.377 mi
Registration #17	2015-08-20	51.377 mi
Registration #18	2015-08-20	51.377 mi
Registration #19	2015-08-20	51.377 mi
Registration #20	2015-08-20	51.377 mi
Registration #21	2015-08-20	51.377 mi
Registration #22	2015-08-20	51.377 mi
Registration #23	2015-08-20	51.377 mi
Registration #24	2015-08-20	51.377 mi
Registration #25	2015-08-20	51.377 mi
Registration #26	2015-08-20	51.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1445 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number

D118628