



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D SE LUX
Colour	Grey
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	39.2 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-10-23
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-04
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #16	2023-11-02 14:07
MOT test number	368385316807
Result	✓ Passed
Next expiry date	2024-11-04

MOT #15	2023-11-02 14:07
MOT test number	484301553076
Result	✗ Failed
Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14	2022-10-24 08:20
MOT test number	641656408422
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2021-11-05 15:30
MOT test number	687674717126
Result	✓ Passed

**MOT #12**

2021-09-18 11:03

MOT test number

645387588549

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2021-09-18 10:32

MOT test number

948293005954

Result

✗ Failed

Fail Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Nearside Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))**MOT #10**

2020-08-11 11:32

MOT test number

432641748492

Result

✓ Passed

MOT #9

2020-08-05 14:30

MOT test number

988443162407

Result

✗ Failed

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #8** 2019-03-12 11:21**MOT test number** 519968809186**Result** ✓ Passed**MOT #7** 2017-09-21 08:51**MOT test number** 413534106038**Result** ✓ Passed**MOT #6** 2016-09-24 09:21**MOT test number** 822684752978**Result** ✓ Passed**MOT #5** 2015-10-10 08:07**MOT test number** 462026754031**Result** ✓ Passed**MOT #4** 2014-09-13 09:03**MOT test number** 369206654216**Result** ✓ Passed**MOT #3** 2013-09-16 10:09**MOT test number** 655719853298**Result** ✓ Passed**Notice** NSR tyre cracked/perished on side wall and between tread blocks**Advice** Offside Rear Trailing arm synthetic mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm synthetic mounting deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2012-09-19 11:43
MOT test number	226023762282
Result	✓ Passed
Advice	Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1	2011-09-19 10:01
MOT test number	825962961251
Result	✓ Passed
Advice	Nearside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

X

Untaxed

Tax expired:
17 February 2024

✓

MOT

Expires:
4 November 2024

Tax status	Expired at 17 February 2024
Days left	72 days too late
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-20
Last registration	2023-11-02
Complete history	See info



Registration #1	2008-09-20	16 mi
Registration #2	2011-09-19	33.139 mi
Registration #3	2012-09-19	44.507 mi
Registration #4	2013-09-16	57.259 mi
Registration #5	2014-09-13	83.752 mi
Registration #6	2015-10-10	90.179 mi
Registration #7	2016-09-24	95.341 mi
Registration #8	2017-09-21	101.909 mi
Registration #9	2019-03-12	106.981 mi
Registration #10	2019-03-12	106.981 mi
Registration #11	2019-03-12	106.981 mi
Registration #12	2019-03-12	106.981 mi
Registration #13	2019-03-12	106.981 mi
Registration #14	2019-03-12	106.981 mi
Registration #15	2019-03-12	106.981 mi
Registration #16	2019-03-12	106.981 mi
Registration #17	2019-03-12	106.981 mi
Registration #18	2019-03-12	106.981 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1490 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1583 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	649107