



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 280 LR P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	310 Nm at 1.300 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-04
Pictures	34
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-05-23
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	45
Total items failed	4

MOT #16	2023-05-24 13:22
MOT test number	873597244964
Result	✓ Passed
Next expiry date	2024-05-23
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2023-05-24 13:22
MOT test number	874651623648
Result	✗ Failed
Pass with rectification	Nearside Side repeater not working (4.4.1 (a) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14** 2022-05-16 12:04**MOT test number** 130449341197**Result** ✓ Passed**Advice** Nearside Rear tyre worn on inner edge, perishing**Advice** Offside Rear tyre worn on inner edge, perishing**MOT #13** 2022-05-13 11:33**MOT test number** 612805948872**Result** ✗ Failed**MAJOR** Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear tyre worn on inner edge, perishing**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear tyre worn on inner edge, perishing**MOT #12** 2021-07-01 15:30**MOT test number** 602032871777**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** O/s/f tyre on limit advise early replacement**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #11**

2021-07-01 10:03

**MOT test number**

996630272095

**Result****✗ Failed****Advice** O/s/f tyre on limit advise early replacement**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #10**

2020-05-27 15:28

**MOT test number**

935849816867

**Result****✓ Passed****Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
ARM REAR BUSH (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
ARM REAR BUSH (5.3.4 (a) (i))**MOT #9**

2020-05-27 11:03

**MOT test number**

389652756654

**Result****✗ Failed****Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
ARM REAR BUSH (5.3.4 (a) (i))**MAJOR** Offside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
ARM REAR BUSH (5.3.4 (a) (i))**MAJOR** Nearside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Wheel hub spigot mounting slightly worn slight movement in bearing (5.2.1 (b) (i))

**MOT #8**

2019-05-24 09:30

**MOT test number**

128059702385

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7**

2019-05-23 08:12

**MOT test number**

223288463413

**Result**

✗ Failed

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6**

2018-05-24 14:32

**MOT test number**

390163159483

**Result**

✓ Passed

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5** 2018-05-24 12:49**MOT test number** 190078289088**Result** ✗ Failed**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #4** 2017-05-26 14:37**MOT test number** 659950196587**Result** ✓ Passed**MOT #3** 2016-05-12 08:51**MOT test number** 869085092995**Result** ✓ Passed**Advice** Both rear tyres outer side walls perished**MOT #2** 2015-05-01 11:15**MOT test number** 445491825189**Result** ✓ Passed**MOT #1** 2015-05-01 11:15**MOT test number** 617481025190**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
23 May 2024

<b>Tax status</b>	Valid until 1 September
-------------------	-------------------------

<b>Days left</b>	124
------------------	-----

<b>MOT expiry date</b>	23 May 2024
------------------------	-------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-05-01
Last registration	2023-05-24
Complete history	<a href="#">See info</a>



Registration #1	2012-05-01	26 mi
Registration #2	2015-05-01	30.699 mi
Registration #3	2016-05-12	40.744 mi
Registration #4	2017-05-26	51.739 mi
Registration #5	2018-05-24	61.882 mi
Registration #6	2018-05-24	61.882 mi
Registration #7	2019-05-23	71.438 mi
Registration #8	2019-05-24	71.438 mi
Registration #9	2020-05-27	79.544 mi
Registration #10	2020-05-27	79.544 mi
Registration #11	2020-05-27	79.544 mi
Registration #12	2020-05-27	79.544 mi
Registration #13	2020-05-27	79.544 mi
Registration #14	2020-05-27	79.544 mi
Registration #15	2020-05-27	79.544 mi
Registration #16	2020-05-27	79.544 mi
Registration #17	2020-05-27	79.544 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BM22795