




report date: 2024-03-28

General information

Make	FIAT
Model	500 LOUNGE
Colour	White
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-03
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #6 2023-12-22 11:01

MOT test number 743903154343

Result ✔ Passed

Next expiry date 2025-01-03

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking to tread & sidewalls (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking to tread & sidewalls (5.2.3 (d) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear wiper rubber split

MOT #5 2023-01-04 10:12

MOT test number 474266928002

Result ✔ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #4	2021-12-17 14:40
MOT test number	343078872558
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3	2021-12-17 13:44
MOT test number	926351720836
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2	2020-12-17 01:51
MOT test number	474741934500
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1	2020-03-16 12:51
MOT test number	315744282888
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
3 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-




Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-03-28
Current registration	XXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-31
Last registration	2023-12-22
Complete history	See info



Registration #1	2017-03-31	16 mi
Registration #2	2020-03-16	12.895 mi
Registration #3	2020-12-17	14.809 mi
Registration #4	2023-03-22	15.277 mi
Registration #5	2023-06-22	15.277 mi
Registration #6	2023-09-22	15.277 mi
Registration #7	2023-12-22	15.277 mi
Registration #8	2023-12-22	15.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number

2181262