



RENAULT

 **MJI4ZSE**


report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-02-04
Pictures	5
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-13
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	33
Total items failed	5

MOT #13	2023-09-14 08:46
MOT test number	735437248238
Result	✓ Passed
Next expiry date	2024-09-13
Advice	Under trays fitted obscuring some under vehicle components

MOT #12	2023-09-08 12:12
MOT test number	468668552008
Result	✗ Failed
Minor	Nearside Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Under trays fitted obscuring some under vehicle components
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11** 2023-07-12 12:44**MOT test number** 371527407026**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust mounting defective Close to flexi (6.1.2 (a))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #10** 2022-09-10 10:34**MOT test number** 625878961978**Result** ✓ Passed**MOT #9** 2022-09-09 11:06**MOT test number** 420707150446**Result** ✗ Failed**DANGEROUS** Offside Front Tyre has ply or cords exposed 205/55/16. (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test**MOT #8** 2021-09-14 14:29**MOT test number** 110828439482**Result** ✓ Passed

**MOT #7** 2020-08-01 10:51**MOT test number** 901770268723**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2019-08-03 11:18**MOT test number** 334258504952**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2019-08-02 11:05**MOT test number** 877967970631**Result** ✗ Failed**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #4** 2018-07-26 14:05**MOT test number** 608398577388**Result** ✓ Passed

**MOT #3** 2018-07-24 12:31**MOT test number** 558561056117**Result** ✗ Failed

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #2** 2017-07-28 14:45**MOT test number** 386406722284**Result** ✓ Passed

**Advice** N/s/f o/s/r and n/s/r tyres perished.

**Advice** Nearside Front Outer tyre wall split.

**MOT #1** 2017-07-28 08:46**MOT test number** 462573307944**Result** ✗ Failed

**Advice** All tyre perishing.

**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Offside Rear rear brake binding (3.7.B.1)

**Advice** Offside Rear Nail in tyre

**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Nearside Front Outer tyre wall split.

**Fail** Nearside Rear rear brake binding (3.7.B.1)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
13 September 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	13 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-05-29
Last registration	2023-09-14
Complete history	<a href="#">See info</a>



Registration #1	2014-05-29	18 mi
Registration #2	2017-07-28	20.781 mi
Registration #3	2017-07-28	20.782 mi
Registration #4	2018-07-24	31.566 mi
Registration #5	2018-07-26	31.753 mi
Registration #6	2019-08-02	40.535 mi
Registration #7	2019-08-03	40.535 mi
Registration #8	2020-08-01	49.001 mi
Registration #9	2020-08-01	49.001 mi
Registration #10	2020-08-01	49.001 mi
Registration #11	2020-08-01	49.001 mi
Registration #12	2020-08-01	49.001 mi
Registration #13	2020-08-01	49.001 mi
Registration #14	2020-08-01	49.001 mi
Registration #15	2020-08-01	49.001 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	D510601