





report date: 2024-03-29

General information

Make	AUDI
Model	A5 TFSI SE
Colour	Blue
Year of manufacture	2009
Top speed	150 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	211 BHP
Max. torque	350 Nm at 4.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-01-27
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT histo	orv
-----------	-----

MOT expiry date	2025-02-28
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #17	2024-02-29 12:22
MOT test number	146300664651
Result	✓ Passed
Next expiry date	2025-02-28
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2023-02-24 16:19
MOT test number	146962150017
Result	✓ Passed

MOT #15	2022-02-25 16:03
MOT test number	271938654687
Result	✓ Passed

MOT #14	2022-02-25 16:03
MOT test number	284522238767
Result	× Failed

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 3/13



MOT #13 2021-02-08 17:09

MOT test number 256525082991

Result \rightarrow Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2021-02-08 15:02

MOT test number 933593965851

Result X Failed

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-11-30 13:17

MOT test number 487283320836

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Shock absorbers light misting of oil or has limited damping effect both weak (5.3.2 (b))

Advice Suspension arm pin or bush worn but not resulting in excessive movement all (5.3.4 (a) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill / a pillar base (5.3.6 (a) (i))

MOT #10 2019-12-09 10:04

MOT test number 575088776731

Result
✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn to 3mm approx, legal limit is 1.6mm (5.2.3 (e))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 4/13



MOT #9 2018-08-31 08:35

MOT test number 563177528596

Result \rightarrow Passed

Minor

Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8 2018-08-28 10:44

MOT test number 707286242756

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner shoulder (5.2.3 (d) (i))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7 2017-08-22 12:03

MOT test number 366799377744

Result

Passed

Advice Covers fitted to underside of vehicle

MOT #6 2016-08-24 12:06

MOT test number 998525958923

MOT #5 2016-08-24 11:36

MOT test number 741268072494

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 5/13



MOT #2

GJ59EXU report date: 2024-03-29

2013-09-02 12:49

MOT #4	2015-08-13 13:04
MOT test number	117185025282
Result	✓ Passed
MOT #3	2014-08-20 14:47
MOT test number	947022534202
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT test number	306605243252
Result	✓ Passed
MOT #1	2012-08-16 11:34
MOT test number	715199622259
Result	✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NIP ZIS UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-01
Last registration	2024-02-29
Complete history	See info



Registration #1	2009-09-01	17 mi
Registration #2	2012-08-16	53.360 mi
Registration #3	2013-09-02	69.754 mi
Registration #4	2014-08-20	85.796 mi
Registration #5	2015-08-13	101.079 mi
Registration #6	2016-08-24	115.716 mi
Registration #7	2016-08-24	115.716 mi
Registration #8	2017-08-22	129.853 mi
Registration #9	2018-08-28	136.864 mi
Registration #10	2018-08-31	136.893 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1854 mm
Height	1383 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1630 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	CDN 053231

CarCheck.co.uk page 13/13