





report date: 2024-03-28

General information

Make	MAZDA
Model	6 D SPORT NAV
Colour	White
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	173 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-11

Pictures 22

Listing price <u>View report</u>









source: heycar.co.uk


Entry 1

Date	2021-07-06
D' I	21

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



SY66MVL report date: 2024-03-28

MOT history

MOT expiry date	2024-07-25
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #6	2023-06-29 14:32	
MOT test number	732028384926	
Result	✓ Passed	
Next expiry date 2024-07-25 Advice Suspension arm pin or bush worn but not resulting in excessive movement both front arms rear		
bushes (5.3.4 (a) (i))		
Advice Nearside Front Outer sidewall slightly damaged		
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt		

MOT #5	2022-06-30 11:51
MOT test	number 247306261007
Result	✓ Passed
Advice (c))	Nearside Rear Brake pipe corroded, covered in grease or other material covered in grease (1.1.11
Advice (c))	Offside Front Brake pipe corroded, covered in grease or other material covered in grease (1.1.11
Advice (c))	Offside Rear Brake pipe corroded, covered in grease or other material covered in grease (1.1.11
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice (c))	Nearside Front Brake pipe corroded, covered in grease or other material covered in grease (1.1.11

MOT #4	2021-07-26 14:11
MOT test number	168265670162
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-07-08 13:39

MOT test number 561476111648

Result

× Failed

Fail Offside Front Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #2 2020-09-04 15:01

MOT test number 292747879182

Result ✓ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #1 2019-09-05 13:28

MOT test number 593775398534

CarCheck.co.uk page 4/11



SY66MVL report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



SY66MVL report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

SY66MVL

report date: 2024-03-28

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MAZDA had different number plates.

More info >

CarCheck.co.uk page 8/11



SY66MVL report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-12
Last registration	2023-06-29
Complete history	See info



Registration #1	2016-09-12	9 mi
Registration #2	2019-09-05	27.530 mi
Registration #3	2020-09-04	33.726 mi
Registration #4		11.777 es
Registration #5	2021-07-08	36.676 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2750 mm
Kerb weight	1430 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	SH 30662811

CarCheck.co.uk page 11/11