



**YEI4AZO**

report date: 2024-03-28

General information

Make	FORD
Model	S-MAX
Colour	White
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-01-05
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #10	2024-01-03 17:13
MOT test number	422903600972
Result	✓ Passed
Next expiry date	2025-01-05
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9	2022-12-30 15:02
MOT test number	737973882383
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-01-05 14:47
MOT test number	529070713181
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2021-01-06 17:25
MOT test number	551126728434
Result	✓ Passed

**MOT #6** 2020-10-31 11:30**MOT test number** 241452309679**Result** ✓ Passed**MOT #5** 2020-10-31 11:30**MOT test number** 294535253770**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #4** 2019-05-16 09:13**MOT test number** 744717736730**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2018-05-18 09:09**MOT test number** 798107612203**Result** ✓ Passed**Advice** Nearside Front tyre perished on outer wall**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Rear tyre perished outer wall



MOT #2	2018-05-18 09:09
MOT test number	535257739064
Result	✗ Failed
Advice	Nearside Front tyre perished on outer wall
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Rear tyre perished outer wall
Advice	Parking brake lever has little reserve travel (3.1.6b)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2017-03-27 15:11
MOT test number	390444744658
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
5 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	5 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-29
Last registration	2024-01-03
Complete history	<a href="#">See info</a>



Registration #1	2014-04-29	20 mi
Registration #2	2017-03-27	88.134 mi
Registration #3	2018-05-18	95.376 mi
Registration #4	2018-05-18	95.376 mi
Registration #5	2019-05-16	103.977 mi
Registration #6	2020-10-31	118.210 mi
Registration #7	2020-10-31	118.210 mi
Registration #8	2020-10-31	118.210 mi
Registration #9	2020-10-31	118.210 mi
Registration #10	2020-10-31	118.210 mi
Registration #11	2020-10-31	118.210 mi
Registration #12	2020-10-31	118.210 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	70 l
Number of axles	2
Engine number	EA09685