





report date: 2024-03-28

## General information

Mala	MEDCEDEC
Make	MERCEDES
Model	S-Class S350
Colour	Silver
Year of manufacture	2003
Top speed	153 mph
0 - 60 mph	7.3 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	245 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.724 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.2 mpg
Consumption extra urban	34.9 mpg
Consumption combined	25.5 mpg
CO2 emission	266 g/km
CO2 label	М



CarCheck.co.uk page 1/13



# Internet history

## Entry 2

Date 2021-10-27

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-10-25

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-08-20
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	35
Total items failed	6

MOT #18	2021-07-27 16:07
MOT test number	468948126110
Result	<b>✓</b> Passed
Next expiry date	2022-08-20
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #17	2021-07-26 14:08
MOT test number	939070349451
Result	<b>X</b> Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.	1.14 (a) (ii))
Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Front Headlamp has a product on the light source so that the light output is severely side (4.1.4 (b))	reduced both
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre perished (5.2.3 (e	))

CarCheck.co.uk page 3/13



MOT #16 2020-07-23 14:37

**MOT test number** 582064979369

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2019-07-26 16:36

**MOT test number** 901981043946

Result \sqrt{Passed}

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14** 2018-07-25 16:51

MOT test number 848310602121

Result 

Passed

**Advice** Engine cover / under trays fitted

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2017-07-21 11:34

**MOT test number** 862989057095

**Result** 
✓ Passed

**Advice** Offside Play in steering rack inner joint(s)

CarCheck.co.uk page 4/13



**MOT #12** 2016-07-22 14:19

**MOT test number** 562467319982

**Result** ✓ Passed

**Advice** Engine cover fitted obscuring some components in engine bay

**Advice** Oil leak

**Advice** Under tray fitted obscuring some underside components

**Advice** Nearside Front Tyre worn close to the legal limit sides 1.8 mm (4.1.E.1)

**MOT #11** 2015-07-22 14:48

MOT test number 788863905255

Result \square Passed

**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #10 2014-08-21 12:24

MOT test number 367143934266

**Notice** Offside inner tie-rod has slight play

**Notice** Under-trays fitted obscuring some underside components

**MOT #9** 2013-07-19 10:28

**MOT test number** 987430403206

**Result** 
✓ Passed

**Advice** Offside Outer Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A'

(8.3.1d)

Notice Oil leak

CarCheck.co.uk page 5/13



KY53HDN

report date: 2024-03-28

MOT #8	2012-07-18 15:20
--------	------------------

**MOT test number** 345720902231

MOT #7 2011-07-13 11:06

**MOT test number** 918014191116

**Result** ✓ Passed

**MOT #6** 2010-07-14 10:48

**MOT test number** 342065290193

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2009-07-21 10:52

**MOT test number** 442382209222

**Result** ✓ Passed

MOT #4 2008-07-21 13:16

MOT test number 180973408224

**Result** ✓ Passed

**Notice** Play to offside front loer outer rear balljoint

Advice Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)

**Notice** Spare tyre worn

Advice Nearside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A'

(8.3.1d)

**Notice** Front brake discs worn

CarCheck.co.uk page 6/13



MOT #3 2007-07-18 12:33

**MOT test number** 973719197177

**Result** ✓ Passed

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2006-08-11 08:55

**MOT test number** 234263026224

**Result** ✓ Passed

MOT #1 2006-08-11 08:55

**MOT test number** 103293226288

Result X Failed

**Pass with rectification** Nearside Front Headlamp aim too high (1.8)

**Pass with rectification** Offside Front Headlamp aim too high (1.8)

CarCheck.co.uk page 7/13



## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Category

Туре

**Date** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
********	
***************************************	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	IK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-09-01
Last registration	2021-07-27
Complete history	See info



2003-09-01	28 mi
2006-08-11	25.230 mi
2007-07-18	29.842 mi
2008-07-21	34.376 mi
2009-07-21	37.555 mi
2010-07-14	39.440 mi
2011-07-13	40.991 mi
2012-07-18	42.944 mi
2013-07-19	44.608 mi
2014-08-21	46.398 mi
	11.777 mi
	11.777 es
	11.777 es
	11.777 es
	11.777 es
	11.777 es
	77.777-66 77.777-66 77.777-66
	11.777-00 11.777-00 11.777-00 11.777-00
	77,777-66 77,777-66 77,777-66 77,777-66
	2006-08-11 2007-07-18 2008-07-21 2009-07-21 2010-07-14 2011-07-13 2012-07-18 2013-07-19 2014-08-21

More info >

CarCheck.co.uk page 12/13



# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1886 mm
Height	1497 mm
Length	5113 mm
Wheel base	2965 mm
Kerb weight	1810 kg

# Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11297231579613

CarCheck.co.uk page 13/13