



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Grey
Year of manufacture	2009
Top speed	119 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	36
Total items failed	2

MOT #18	2023-10-26 14:51
MOT test number	896046236259
Result	✓ Passed
Next expiry date	2024-11-18
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))

MOT #17	2023-10-23 15:21
MOT test number	883372672019
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))
MAJOR	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #16**

2022-11-16 12:31

MOT test number

573676816832

Result

✓ Passed

- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view Chip in windscreen (3.2 (a) (i))
- Advice** Offside Front Seat belt retracting slowly
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear console bush split (5.3.4 (a) (i))

MOT #15

2022-11-09 14:41

MOT test number

395210850513

Result

✗ Failed

- Advice** Offside Front Seat belt retracting slowly
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 3mm (5.2.3 (d) (i))
- MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear console bush split (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view Chip in windscreen (3.2 (a) (i))
- MAJOR** Offside Front Side repeater not working mirror led not working (4.4.1 (a) (ii))

**MOT #14** 2021-11-19 15:02**MOT test number** 399441822718**Result** ✓ Passed**MOT #13** 2021-11-19 15:02**MOT test number** 864382909917**Result** ✗ Failed**Pass with rectification** Offside Front Direction indicator not working (4.4.1 (a) (ii))**MOT #12** 2021-07-06 12:17**MOT test number** 772518886150**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All four discs deteriorated (1.1.14 (a) (ii))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #11** 2021-07-06 10:50**MOT test number** 611414573460**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All four discs deteriorated (1.1.14 (a) (ii))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #10** 2020-07-08 14:54**MOT test number** 455364505720**Result** ✓ Passed

**MOT #9** 2020-07-01 13:42**MOT test number** 868533045479**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Centre bush (5.3.4 (a) (i))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2019-07-10 13:10**MOT test number** 231231341970**Result** ✓ Passed**MOT #7** 2018-07-06 10:25**MOT test number** 257265234075**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Nail in tyre**Advice** Rear tyres cracked**MOT #6** 2017-07-07 11:13**MOT test number** 856519499895**Result** ✓ Passed**MOT #5** 2016-07-15 14:40**MOT test number** 850688950081**Result** ✓ Passed



MOT #4 2015-07-03 12:30

MOT test number 457164285141

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-07-11 09:22

MOT test number 396322294121

Result ✓ Passed

MOT #2 2013-07-03 16:32

MOT test number 518414283109

Result ✓ Passed

MOT #1 2012-07-04 14:01

MOT test number 149106382121

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
18 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	18 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXX
Plate since	2024-03-29
Current registration	 XXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-05-11
Last registration	2023-10-26
Complete history	See info



Registration #1	2009-05-11	9 mi
Registration #2	2012-07-04	20.865 mi
Registration #3	2013-07-03	25.976 mi
Registration #4	2014-07-11	30.939 mi
Registration #5	2015-07-03	34.980 mi
Registration #6	2016-07-15	38.305 mi
Registration #7	2017-07-07	41.523 mi
Registration #8	2018-07-06	45.684 mi
Registration #9	2019-07-10	47.480 mi
Registration #10	2020-07-01	58.332 mi
Registration #11	2020-07-01	58.332 mi
Registration #12	2020-07-01	58.332 mi
Registration #13	2020-07-01	58.332 mi
Registration #14	2020-07-01	58.332 mi
Registration #15	2020-07-01	58.332 mi
Registration #16	2020-07-01	58.332 mi
Registration #17	2020-07-01	58.332 mi
Registration #18	2020-07-01	58.332 mi
Registration #19	2020-07-01	58.332 mi
Registration #20	2020-07-01	58.332 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 173871