



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T2
Colour	Blue
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.7 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1	
Date	2021-06-12
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-20
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	64
Total items failed	4

MOT #21	2024-02-21 16:21
MOT test number	126077766033
Result	✓ Passed
Next expiry date	2025-02-20
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20**

2022-11-14 15:54

MOT test number

227517975830

Result

✓ Passed

- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. NSR brake has a low effort (1.2.1 (b) (i))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Offside Upper Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction sticker (3.1 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear unable to check rear seat belts due to items in vehicle
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19

2021-11-15 09:55

MOT test number

386305144758

Result

✓ Passed

- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #18**

2021-11-05 14:49

MOT test number

116755120905

Result**✗ Failed****MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. nsr brake readings low (1.2.1 (b) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #17**

2020-08-28 09:32

MOT test number

454153165310

Result**✓ Passed****Advice** Both rear inner sills corroding**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view chip zone B (3.2 (a) (i))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Minor** Headlamp lens slightly defective both deteriorating (4.1.1 (b) (i))

**MOT #16**

2019-09-02 09:58

MOT test number

610329323351

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside outer sill damaged
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Both sides (5.3.6 (a) (i))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))

MOT #15

2019-09-02 09:58

MOT test number

964628700570

Result

✗ Failed

- Advice** Offside outer sill damaged
- Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Both sides (5.3.6 (a) (i))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2018-09-03 09:16

MOT test number

548595120300

Result

✓ Passed

- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sills (5.3.6 (a) (i))
- Advice** Nearside outer sill damaged

MOT #13

2018-09-03 09:16

MOT test number

820121572600

Result

✗ Failed

- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sills (5.3.6 (a) (i))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Nearside outer sill damaged

MOT #12

2017-08-31 11:48

MOT test number

545290113631

Result

✓ Passed

- Advice** Front brake discs worn
- Advice** Offside rear coil spring corroding
- Advice** Washer jets require adjustment
- Advice** Damage to nearside outer sill
- Advice** Both rear inner sills corroding
- Advice** Rear brake discs worn/corroded

**MOT #11** 2016-09-16 13:33**MOT test number** 570794288417**Result** ✓ Passed**Advice** All brake discs worn/corroded**MOT #10** 2015-09-14 10:34**MOT test number** 524029248778**Result** ✓ Passed**Advice** All brake discs worn/corroded**MOT #9** 2015-09-14 10:34**MOT test number** 918965508272**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** All brake discs worn/corroded**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2014-09-02 15:07**MOT test number** 407465944283**Result** ✓ Passed**Notice** Both rear tyres perished in tread**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Front disc's and pads becoming worn

**MOT #7** 2013-09-10 12:21**MOT test number** 928713553225**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Both rear tyres, outer sidewalls perishing**MOT #6** 2012-09-03 15:00**MOT test number** 226927642231**Result** ✓ Passed**Notice** Both rear tyre sidewalls perished and minor splits appearing**MOT #5** 2011-09-05 15:12**MOT test number** 769218141205**Result** ✓ Passed**MOT #4** 2010-09-15 15:31**MOT test number** 331668750498**Result** ✓ Passed**MOT #3** 2009-09-17 11:14**MOT test number** 311600269419**Result** ✓ Passed**MOT #2** 2008-09-18 14:42**MOT test number** 920402268258**Result** ✓ Passed



MOT #1	2007-08-30 12:32
MOT test number	662022947251
Result	✓ Passed
<div>Notice</div> Front brake pads getting low and slight lip on front discs.	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-01
Last registration	2024-02-21
Complete history	See info



Registration #1	2004-09-01	29 mi
Registration #2	2007-08-30	17.143 mi
Registration #3	2008-09-18	22.869 mi
Registration #4	2009-09-17	24.784 mi
Registration #5	2010-09-15	26.227 mi
Registration #6	2011-09-05	27.668 mi
Registration #7	2012-09-03	30.004 mi
Registration #8	2013-09-10	31.979 mi
Registration #9	2014-09-02	33.879 mi
Registration #10	2015-09-14	36.084 mi
Registration #11	2015-09-14	36.084 mi
Registration #12	2016-09-16	38.448 mi
Registration #13	2016-09-16	38.448 mi
Registration #14	2016-09-16	38.448 mi
Registration #15	2016-09-16	38.448 mi
Registration #16	2016-09-16	38.448 mi
Registration #17	2016-09-16	38.448 mi
Registration #18	2016-09-16	38.448 mi
Registration #19	2016-09-16	38.448 mi
Registration #20	2016-09-16	38.448 mi
Registration #21	2016-09-16	38.448 mi
Registration #22	2016-09-16	38.448 mi
Registration #23	2016-09-16	38.448 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	3ZZU464952