



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-08-11
Pictures	16
Listing price	<a href="#">View report</a>



FINANCE INFORMATION			
		£122.89 per month	
OF REPRESENTATIVE EXAMPLE			
CASH PRICE	£1,499.00	FIXED INTEREST RATE	£1.99% PA
DEPOSIT	£100.00	REPRESENTATIVE APR	£1,500.00
TOTAL AMOUNT OF CREDIT	£1,399.00	DURATION OF AGREEMENT	60 MONTHS
TOTAL AMOUNT PAYABLE	£1,737.00	INITIAL PAYMENT	£122.89
ADMINISTRATION FEE	£0.00	60 MONTHLY PAYMENTS	£122.89
OPTION TO PURCHASE FEE	£1.00	FINAL PAYMENT	£122.89



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-28
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	18
Total items failed	6

## MOT #11 2023-08-31 10:07

MOT test number 650663463948

Result ✓ Passed

Next expiry date 2024-09-28

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #10 2023-08-31 10:07

MOT test number 189843865729

Result ✗ Failed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2022-09-03 08:05**MOT test number** 269726961985**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #8** 2021-09-29 12:51**MOT test number** 461743794047**Result** ✓ Passed**Advice** Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))**MOT #7** 2021-09-27 09:36**MOT test number** 492928598396**Result** ✗ Failed**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))**MOT #6** 2020-09-21 10:05**MOT test number** 251430125630**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edges (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edges (5.2.3 (e))**MOT #5** 2019-09-19 15:15**MOT test number** 165032922336**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2019-09-19 09:18**MOT test number** 866607123902**Result** ✗ Failed**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #3** 2018-09-14 09:51**MOT test number** 411823106936**Result** ✓ Passed**MOT #2** 2017-09-12 08:06**MOT test number** 389720669471**Result** ✓ Passed**MOT #1** 2017-09-12 08:06**MOT test number** 824754394152**Result** ✗ Failed**Pass with rectification** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
28 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	28 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-29
Last registration	2023-08-31
Complete history	<a href="#">See info</a>



Registration #1	2014-09-29	28 mi
Registration #2	2017-09-12	22.490 mi
Registration #3	2017-09-12	22.490 mi
Registration #4	2018-09-14	33.606 mi
Registration #5	2019-09-19	43.952 mi
Registration #6	2019-09-19	43.952 mi
Registration #7	2020-09-21	48.477 mi
Registration #8	2023-08-31	55.277 mi
Registration #9	2023-08-31	55.277 mi
Registration #10	2023-08-31	55.277 mi
Registration #11	2023-08-31	55.277 mi
Registration #12	2023-08-31	55.277 mi
Registration #13	2023-08-31	55.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D510601