



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA V5
Colour	Blue
Year of manufacture	2002
Top speed	137 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	125 BHP
Max. torque	304 Nm at 3.200 rpm
Engine capacity	2.324 cc
Cylinders	5
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	20.6 mpg
Consumption combined	38.2 mpg
CO2 emission	233 g/km
CO2 label	L







Internet history

Entry 1

Date	2022-06-25
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-13
MOT pass rate	73 %
MOT passed	19
Failed MOT tests	7
Total advice items	47
Total items failed	18

MOT #26	2023-08-15 08:13
MOT test number	394346390045
Result	✓ Passed
Next expiry date	2024-09-13

MOT #25	2023-08-14 08:34
MOT test number	998166991059
Result	✗ Failed

- Fail** Nearside Headlamp aim unable to be tested Due to beam image (4.1.2 (b))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Track rod end ball joint has excessive play Ball joint loose in steering arm. (dangerous) (2.1.3 (b) (i))
- Advice** Offside Headlamp image also poor

MOT #24	2022-09-14 15:26
MOT test number	929773822847
Result	✓ Passed
Advice Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))	

**MOT #23**

2022-02-28 12:04

MOT test number

777758428115

Result

✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened both front inner edges (1.1.14 (a) (ii))

Advice Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both front headlight lenses deteriorated

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #22

2021-03-02 09:46

MOT test number

936987465777

Result

✓ Passed

Advice Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front inner edges (1.1.14 (a) (ii))

Advice Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Both front headlight lenses slightly deteriorated

MOT #21

2020-03-09 13:59

MOT test number

937881014425

Result

✓ Passed

Advice Sub-frame pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))

Advice Both headlight lenses slightly deteriorated

Advice Front brake discs slight corrosion on the inner edges

Advice Slight oil leak

Advice Play in steering rack inner joint(s) both front

**MOT #20**

2020-03-05 09:04

MOT test number

394758474755

Result**✗ Failed**

- Advice** Slight oil leak
- Advice** Play in steering rack inner joint(s) both front
- Advice** Offside front door mirror glass deteriorated condition
- Advice** Nearside front tyre is worn on the outer edge [205/55/16/91V]
- Advice** Sub-frame pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))
- Advice** Front brake discs slight corrosion on the inner edges
- Fail** Rear Registration plate insecure (0.1 (a))
- Advice** Both headlight lenses slightly deteriorated
- Fail** Nearside Front Lower Suspension arm pin or bush likely to become detached rear (5.3.4 (a) (ii))

MOT #19

2019-05-31 09:53

MOT test number

856399081977

Result**✓ Passed**

- Advice** Mil light on
- Advice** Some play in both front top strut mounts

MOT #18

2019-05-30 14:18

MOT test number

623004679784

Result**✗ Failed**

- Advice** Mil light on
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Some play in both front top strut mounts

**MOT #17** 2018-05-25 14:33**MOT test number** 426654258374**Result** ✓ Passed**MOT #16** 2018-05-24 10:13**MOT test number** 104602378672**Result** ✗ Failed**Advice** N/s/f tyre worn on inner edge**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** N/s/r side light dim**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (h) (i))**MOT #15** 2017-06-01 13:52**MOT test number** 385612925241**Result** ✓ Passed**Advice** Lift in o/s leg top**Advice** N/s/r tyre close to limit and perished

**MOT #14**

2017-06-01 11:42

MOT test number

747257764685

Result

✗ Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Lift in o/s leg top**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** N/s/r tyre close to limit and perished**MOT #13**

2016-02-19 12:30

MOT test number

759437243479

Result

✓ Passed

Advice Rear Sub-frame has slight play in a pin/bush (2.4.G.2)**Advice** Nearside rear tyre perished and split**Advice** Nearside Front Tyre worn close to the legal limit 1.6mm legal limit (worn on edges) (4.1.E.1)**Advice** Nearside Drive shaft which forms part of the suspension coupling gaiter damaged, but preventing the ingress of dirt (2.4.G.4e)**Advice** Nearside front tyre sidewall damaged**Advice** Offside Front Tyre worn close to the legal limit 1.6mm legal limit (worn on edges) (4.1.E.1)**MOT #12**

2015-03-02 08:50

MOT test number

429001965039

Result

✓ Passed

MOT #11

2014-04-11 17:09

MOT test number

768301904156

Result

✓ Passed

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

**MOT #10** 2014-04-11 12:42**MOT test number** 557791404103**Result** ✗ Failed**Notice** Front bumper insecure**Fail** Nearside Front Body has a projection caused by damage (6.1.C.1)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #9** 2013-03-06 12:44**MOT test number** 106645263489**Result** ✓ Passed**MOT #8** 2012-04-03 11:11**MOT test number** 547334292043**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2011-04-01 10:33**MOT test number** 976691391038**Result** ✓ Passed**MOT #6** 2010-04-02 09:02**MOT test number** 682432690019**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2009-04-02 11:52**MOT test number** 164342299062**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #4	2008-04-04 09:05
MOT test number	224865898033
Result	✓ Passed
MOT #3	2007-03-16 14:11
MOT test number	620015877071
Result	✓ Passed
MOT #2	2007-03-16 09:25
MOT test number	354115877025
Result	✗ Failed
Fail	Nearside Rear Wheel bolt(s) missing (4.2.A.1e)
MOT #1	2006-03-20 14:12
MOT test number	432919376044
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
13 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-05-03
Last registration	2023-08-15
Complete history	See info



Registration #1	2002-05-03	25 mi
Registration #2	2006-03-20	27.578 mi
Registration #3	2007-03-16	31.939 mi
Registration #4	2007-03-16	31.939 mi
Registration #5	2008-04-04	36.237 mi
Registration #6	2009-04-02	40.412 mi
Registration #7	2010-04-02	44.331 mi
Registration #8	2011-04-01	48.004 mi
Registration #9	2012-04-03	51.941 mi
Registration #10	2013-03-06	54.361 mi
Registration #11	2014-04-11	57.590 mi
Registration #12	2014-04-11	57.590 mi
Registration #13	2015-03-02	61.171 mi
Registration #14	2016-02-19	65.760 mi
Registration #15	2016-03-20	65.760 mi
Registration #16	2016-03-20	65.760 mi
Registration #17	2016-03-20	65.760 mi
Registration #18	2016-03-20	65.760 mi
Registration #19	2016-03-20	65.760 mi
Registration #20	2016-03-20	65.760 mi
Registration #21	2016-03-20	65.760 mi
Registration #22	2016-03-20	65.760 mi
Registration #23	2016-03-20	65.760 mi
Registration #24	2016-03-20	65.760 mi
Registration #25	2016-03-20	65.760 mi
Registration #26	2016-03-20	65.760 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1439 mm
Length	4149 mm

Additional information

Number of axles	2
Engine number	AQN015553