



LN55RRY

report date: 2024-03-29

General information

Make	BMW
Model	525 525D SPORT
Colour	Black
Year of manufacture	2005
Top speed	141 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-27
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-06-30
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	27
Total items failed	2

MOT #13	2023-05-31 10:03
MOT test number	903674676815
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2022-07-01 11:30
MOT test number	535134121845
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-08-12 08:10
MOT test number	595225268598
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement most front arm (5.3.4 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement most front arm (5.3.4 (a) (i))

**MOT #10** 2020-09-11 11:39**MOT test number** 162387243044**Result** ✓ Passed**MOT #9** 2019-09-12 14:53**MOT test number** 380314278466**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2018-09-17 08:22**MOT test number** 808750223898**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #7** 2018-09-12 11:36**MOT test number** 530835911429**Result** ✗ Failed**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

**MOT #6** 2017-08-31 16:05**MOT test number** 500053255043**Result** ✓ Passed**MOT #5** 2016-09-03 10:53**MOT test number** 422703645409**Result** ✓ Passed**MOT #4** 2010-12-13 16:35**MOT test number** 470067540357**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Off side front tyre worn inner edge**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-10-16 16:54**MOT test number** 410849189231**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2008-11-27 15:51**MOT test number** 634012038366**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2008-10-14 11:14
MOT test number	374718188254
Result	✓ Passed
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2005-09-01
Last registration	2023-05-31
Complete history	See info



Registration #1	2005-09-01	6 mi
Registration #2	2008-10-14	42.675 mi
Registration #3	2008-11-27	42.694 mi
Registration #4	2009-10-16	48.164 mi
Registration #5	2010-12-13	60.918 mi
Registration #6	2016-09-03	77.033 mi
Registration #7	2017-08-31	85.486 mi
Registration #8	2018-09-12	99.875 mi
Registration #9	2019-05-29	99,875 mi
Registration #10	2020-05-29	99,875 mi
Registration #11	2021-05-29	99,875 mi
Registration #12	2022-05-29	99,875 mi
Registration #13	2023-05-31	99,875 mi
Registration #14	2023-05-31	99,875 mi
Registration #15	2023-05-31	99,875 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1685 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	30596011