



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2013
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-29
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	27
Total items failed	7

MOT #10	2023-10-30 16:31
---------	------------------

MOT test number	859787199285
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-29
------------------	------------

- Minor

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Rear Suspension arm pin or bush worn but not resulting in excessive movement Near/Offside (5.3.4 (a) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement Near/Offside (5.3.4 (a) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2023-10-30 10:55

**MOT test number**

454920956431

**Result****✗ Failed**

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Near/Offside (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Near/Offside (5.3.4 (a) (i))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8**

2022-10-25 12:20

**MOT test number**

427761242438

**Result****✓ Passed**

**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #7**

2021-10-28 14:18

**MOT test number**

159360580058

**Result****✓ Passed**

**MOT #6**

2020-02-01 09:50

**MOT test number**

150758066031

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pedal wearing smooth (1.1.2 (c))**MOT #5**

2020-01-31 10:50

**MOT test number**

675260360061

**Result**

✗ Failed

**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4**

2018-11-24 13:21

**MOT test number**

356205537514

**Result**

✓ Passed

**MOT #3** 2018-11-24 10:04**MOT test number** 199947281451**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Fail** Front Undertray likely to become detached (6.2.1 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**MOT #2** 2017-11-25 09:27**MOT test number** 366946153416**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2016-12-03 10:28**MOT test number** 173559773900**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
29 October 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	29 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-04
Last registration	2023-10-30
Complete history	<a href="#">See info</a>



Registration #1	2013-12-04	26 mi
Registration #2	2016-12-03	55.909 mi
Registration #3	2017-11-25	68.204 mi
Registration #4	2018-11-24	84.031 mi
Registration #5	2018-11-24	84.031 mi
Registration #6	2020-01-31	101.464 mi
Registration #7	2023-10-30	101.464 mi
Registration #8	2023-10-30	101.464 mi
Registration #9	2023-10-30	101.464 mi
Registration #10	2023-10-30	101.464 mi
Registration #11	2023-10-30	101.464 mi
Registration #12	2023-10-30	101.464 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDDZ211384