



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 PLUS SDI
Colour	Blue
Year of manufacture	2010
Top speed	88 mph
0 - 60 mph	20.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	140 Nm at 2.200 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-07
Pictures	33
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-26
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	23
Total items failed	9

MOT #16	2023-07-27 12:49
MOT test number	565595917714
Result	✓ Passed
Next expiry date	2024-07-26

MOT #15	2022-06-08 13:37
MOT test number	504696893237
Result	✓ Passed
Advice	Offside Rear Road wheel slightly distorted inner rim bent (5.2.2 (c) (i))

MOT #14	2021-06-21 11:42
MOT test number	400120163757
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases MID BOX (6.1.2 (a))

**MOT #13**

2021-06-21 11:42

**MOT test number**

945206750545

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases MID BOX (6.1.2 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid water added (3.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2020-05-26 10:43

**MOT test number**

568390613700

**Result****✓ Passed****MOT #11**

2019-05-24 14:54

**MOT test number**

865378582127

**Result****✓ Passed**

- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

**MOT #10**

2019-05-23 15:53

**MOT test number**

158503392905

**Result****✗ Failed****Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9**

2018-06-12 12:50

**MOT test number**

508944321091

**Result****✓ Passed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))**Advice** BOTH rear tyres deteriorated**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))**MOT #8**

2017-05-19 08:06

**MOT test number**

722587334373

**Result****✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2017-05-19 08:06**MOT test number** 319430918367**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-06-09 11:33**MOT test number** 857072438291**Result** ✓ Passed**MOT #5** 2015-04-22 14:13**MOT test number** 956462315108**Result** ✓ Passed**MOT #4** 2015-04-22 11:28**MOT test number** 605982415183**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #3** 2014-05-03 11:07**MOT test number** 637113324154**Result** ✓ Passed**MOT #2** 2014-05-03 10:00**MOT test number** 696953724199**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Emissions not tested (7.0)



MOT #1	2013-04-17 12:07
MOT test number	906587803114
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
26 July 2024

<b>Tax status</b>	Valid until 1 March
-------------------	---------------------

<b>Days left</b>	306
------------------	-----

<b>MOT expiry date</b>	26 July 2024
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>EU10GXG</b>
Plate since	2024-03-29
Current registration	<b>EU10GXG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-12
Last registration	2023-07-27
Complete history	<a href="#">See info</a>



Registration #1	2010-05-12	14 mi
Registration #2	2013-04-17	38.235 mi
Registration #3	2014-05-03	48.709 mi
Registration #4	2014-05-03	48.709 mi
Registration #5	2015-04-22	60.414 mi
Registration #6	2015-04-22	60.414 mi
Registration #7	2016-06-09	77.074 mi
Registration #8	2017-05-19	91.628 mi
Registration #9	2017-05-19	91.628 mi
Registration #10	2018-05-29	91.628 mi
Registration #11	2018-05-29	91.628 mi
Registration #12	2018-05-29	91.628 mi
Registration #13	2018-05-29	91.628 mi
Registration #14	2018-05-29	91.628 mi
Registration #15	2018-05-29	91.628 mi
Registration #16	2018-05-29	91.628 mi
Registration #17	2018-05-29	91.628 mi
Registration #18	2018-05-29	91.628 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Kerb weight	1465 kg
Max. allowed weight	2232 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2

**Number of axles**

2

**Engine number**

BST104659