





report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA SE TINO
Colour	Red
Year of manufacture	2004
Top speed	108 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I



CarCheck.co.uk page 1/14



YP54YHX report date: 2024-03-29

Internet history


Entry 1

Date 2022-06-01

Pictures 33

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



YP54YHX
report date: 2024-03-29

MOT history

MOT expiry date	2024-12-16
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	30
Total items failed	5

***	****
MOT #20	2023-12-04 11:57
MOT test number	489445638559
Result	✓ Passed
Next expiry date	2024-12-16
Advice Rear Brake disc worn, pitted or scored, but not seriously weaken	ned Both Rear (1.1.14 (a) (ii))

MOT #	19	2023-11-20 11:27
MOT te	st number	338081222504
Result		🗙 Failed
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advic	Rear Brake disc worn, pitted or scored, but not seriously weakened Both Rear ((1.1.14 (a) (ii))

MOT #18	2022-12-06 11:02
MOT test number	333126933315
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing 205/55 ZR16 94W Perished) (5.2.3 (d) (ii))	XL Budget (Slightly
Advice Offside Rear Tyre slightly damaged/cracking or perishing 205/55 ZR16 94W XL Perished) (5.2.3 (d) (ii))	_ Budget (Slightly
Advice Central Heat shield loose	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both Rear	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #17 2022-11-29 09:18

MOT test number 194230415001

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both Rear (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 205/55 ZR16 94W XL Budget (Slightly

Perished) (5.2.3 (d) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 205/55 R16 91H Michelin (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 205/55 ZR16 94W XL Budget (Slightly Perished) (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing 205/55 R16 91H Michelin (Slightly Perished) (5.2.3 (d) (ii))

Advice Central Heat shield loose

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #16 2021-11-24 13:25

MOT test number 989199893339

Result Passed

Advice Plastic sill covers fitted

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #15 2020-12-15 10:25 **MOT** test number 366741334319 ✓ Passed Result **Advice** Rear Exhaust shield loose Advice Offside Rear Brakepipe to the brakehose corroded Advice Offside Front Coil spring worn (5.3.1 (b) (i)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Brakepipe to the brakehose corroded Advice Nearside Rear Handbrake efforts significantly lower than its opposite

 MOT #14
 2019-12-17 13:54

 MOT test number
 303605991527

 Result
 ✓ Passed

MOT test number

Fail Emissions not tested exhaust blowing (8.2.1.2 (d))

Fail Exhaust has a major leak of exhaust gases towards rear (6.1.2 (a))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both inners corroded (1.1.14 (a) (ii))

MOT #12

MOT test number

675544292886

Result

Advice Rear Exhaust noisy (8.1.1 (a))

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #11	2017-11-25 11:14

MOT test number 441724017703

MOT #10 2016-12-08 10:14

MOT test number 190928952704

Result

Passed

MOT #9 2015-12-01 11:25

MOT test number 686246820068

Result
✓ Passed

Advice Both rear tyres wearing low

MOT #8 2014-11-15 10:56

MOT test number 708939414304

Result

Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #7 2013-12-14 13:02

MOT test number 856018543354

Result \(\sqrt{Passed} \)

Notice Nail in nearside rear tyre

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2012-11-28 14:15

MOT test number 197723932391

Result
✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #5	2011-11-19 10:56
MOT test number	257233421311
Result	✓ Passed
MOT #4	2010-11-16 10:21
MOT test number	283040620399
Result	✓ Passed
MOT #3	2009-11-18 10:21
MOT test number	491242729325
Result	✓ Passed
MOT #2	2008-11-28 11:34
MOT test number	161673738312
Result	✓ Passed
MOT #1	2007-11-26 17:27
MOT test number	730590437363
Result	✓ Passed
Notice Both front tyres getting close to limit	
Notice Wipers slow to clear screen of fluid	

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check

Tax expired: 7 March 2024





Expires: 16 December 2024

Tax status	Expired at 7 March 2024
Days left	54 days too late
MOT expiry date	16 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



YP54YHX report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



YP54YHX report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

Owner History	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

page 11/14 CarCheck.co.uk



YP54YHX report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-11-30
Last registration	2023-12-04
Complete history	See info



Registration #1	2004-11-30	19 mi
Registration #2	2007-11-26	24.661 mi
Registration #3	2008-11-28	32.034 mi
Registration #4	2009-11-18	36.375 mi
Registration #5	2010-11-16	43.230 mi
Registration #6	2011-11-19	49.145 mi
Registration #7	2012-11-28	55.375 mi
Registration #8	2013-12-14	62.712 mi
Registration #9	2014-11-15	67.938 mi
Registration #10	2015-12-01	73.791 mi
Registration #11	2016-12-08	81.062 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.177 es
Registration #20 Registration #21		11.77 es 11.77 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1758 mm
Height	1608 mm
Length	4264 mm
Wheel base	2535 mm
Kerb weight	1420 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/1

Number of axles 2
Engine number 357354