



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Red
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-02-05
Pictures	12
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-04-22
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	18
Total items failed	8

MOT #18	2024-04-03 08:52
MOT test number	757270363769
Result	✓ Passed
Next expiry date	2025-04-22

MOT #17	2023-04-03 08:03
MOT test number	264130409498
Result	✓ Passed

MOT #16	2022-04-11 11:43
MOT test number	757402338508
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2021-04-23 10:38
MOT test number	522856733584
Result	✓ Passed

**MOT #14** 2021-04-23 08:28**MOT test number** 699621976959**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #13** 2020-01-17 16:23**MOT test number** 521387949549**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Outer Tyre slightly damaged Sidewall (5.2.3 (d) (ii))

**MOT #12** 2020-01-17 16:23**MOT test number** 321338524047**Result** ✗ Failed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Pass with rectification** Offside Front Windscreen washer not working (3.5 (a))

**Advice** Nearside Front Outer Tyre slightly damaged Sidewall (5.2.3 (d) (ii))

**Pass with rectification** Nearside Front Windscreen washer not working (3.5 (a))

**MOT #11** 2019-01-19 12:07**MOT test number** 443752011890**Result** ✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))

**MOT #10** 2019-01-19 12:07**MOT test number** 255202067957**Result** ✗ Failed

- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2018-01-22 15:32**MOT test number** 602544910568**Result** ✓ Passed**MOT #8** 2018-01-22 15:32**MOT test number** 299026504322**Result** ✗ Failed

- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

**MOT #7** 2017-02-07 11:59**MOT test number** 317897898116**Result** ✓ Passed

**MOT #6** 2017-02-07 10:24**MOT test number** 234743523850**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #5** 2016-02-19 10:04**MOT test number** 839249695146**Result** ✓ Passed**MOT #4** 2015-02-18 12:30**MOT test number** 315769345045**Result** ✓ Passed**Notice** Nearside front tyre low outer edge**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #3** 2015-02-18 12:30**MOT test number** 186719945480**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Nearside front tyre low outer edge**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #2** 2014-02-26 13:01**MOT test number** 258317354053**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)



MOT #1	2013-01-17 15:17
MOT test number	529107913016
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✓  
**MOT**  
  
Expires:  
22 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	22 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AG59A00</b>
Plate since	2019-06-29
Current registration	 <b>AG59A00</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-02-23
Last registration	2024-04-03
Complete history	<a href="#">See info</a>



Registration #1	2010-02-23	21 mi
Registration #2	2013-01-17	21.913 mi
Registration #3	2014-02-26	23.801 mi
Registration #4	2015-02-18	25.393 mi
Registration #5	2016-02-19	30.489 mi
Registration #6	2017-02-07	34.670 mi
Registration #7	2017-02-07	34.673 mi
Registration #8	2018-01-22	37.897 mi
Registration #9	2018-01-22	37.897 mi
Registration #10	2019-01-19	52.565 mi
Registration #11	2019-01-19	52.565 mi
Registration #12	2019-01-19	52.565 mi
Registration #13	2019-01-19	52.565 mi
Registration #14	2019-01-19	52.565 mi
Registration #15	2019-01-19	52.565 mi
Registration #16	2019-01-19	52.565 mi
Registration #17	2019-01-19	52.565 mi
Registration #18	2019-01-19	52.565 mi
Registration #19	2019-01-19	52.565 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721