





## General information

Make	MINI
Model	JOHN COOPER WORKS
Colour	Red
Year of manufacture	2015
Top speed	153 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	231 BHP
Max. torque	320 Nm at 4.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E









# Internet history

Entry 4	
Date	2021-06-25
Pictures	29
Listing price	View report




#### source: yesauto.com

Entry 3	
Date	2021-06-23
Pictures	30
Listing price	View report



#### source: autotrader.co.uk

Entry 2	
Date	2021-06-15
Pictures	29
Listing price	View report



source: yesauto.com

Entry	1
Date	

Pictures CarCheck.co.uk 2021-02-02

8



source: autoonline.co.uk



## MOT history

MOT expiry date	2024-08-19
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	5
Total items failed	1

MOT #7	2023-07-27 13:11
MOT test number	861258575625
Result	✓ Passed
Next expiry date	2024-08-19

МОТ #6	2022-08-06 11:15
MOT test number	598424380418
Result	✓ Passed

MOT #5	2021-08-20 11:03
MOT test number	102529911974
Result	✓ Passed

MOT #4	2020-10-01 13:17
MOT test number	426490222399
Result	✓ Passed

**Minor** Front Windscreen damaged but not adversely affecting driver's view zone A and zone B just within M.O.T. limits. (3.2 (a) (i))





MOT #3	2020-10-01 10:08
MOT test number	137846208456
Result	🗙 Failed
<b>Advice</b> Offside Front Tyre worn close to legal limit/worn on edge also heavily replacing. (5.2.3 (e))	wearing outer edges advise
Advice Nearside Front Tyre worn close to legal limit/worn on edge also heavi (5.2.3 (e))	ly wearing outer edges.
FailNearside Front Tyre has a cut in excess of the requirements deep enough(5.2.3 (d) (i))	h to reach the ply or cords
<b>Minor</b> Front Windscreen damaged but not adversely affecting driver's view z M.O.T. limits. (3.2 (a) (i))	one A and zone B just within
MOT #2	2019-10-02 12:12
MOT test number	133777389949
Result	✓ Passed

MOT #1		2018-05-25 11:54
MOT test	t number	325572127282
Result		Passed
Minor	Nearside Rear Tyre pressure monitoring system warning lamp indicates a fault	t (5.2.3 (h) (i))



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	✓ MOT Expires: 19 August 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	19 August 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





## Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-06
Last registration	2023-07-27
Complete history	<u>See info</u>



Registration #1	2015-06-06	11 mi
Registration #2	2018-05-25	15.992 mi
Registration #3	2019-10-02	19.211 mi
Registration #4	2020-10-01	26.530 mi
Registration #5	2020-10-01	26.530 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 mi




# **EF15WHW** report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
50566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1727 mm
Height	1414 mm
Length	3874 mm
Wheel base	1932 mm
Kerb weight	1295 kg
Max. allowed weight	1700 kg
Additional information	
Fuel tank capacity	44
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11