



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 SPORT DCI L/C P/V
Colour	White
Year of manufacture	2009
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-11-02
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	17
Total items failed	12

MOT #14 2021-11-03 16:10

MOT test number 372465407745

Result ✓ Passed

Next expiry date 2022-11-02

Advice Oil leak [slight]

Advice Showing signs of corrosion on under side of vehicle body

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated front o/s cv boot worn (6.1.7 (g) (i))

Advice Offside Front front o/s drive shaft oil seal leaking

Advice Rear rear number plate worn

MOT #13 2020-10-13 13:52

MOT test number 808682882260

Result ✓ Passed

MOT #12 2020-10-13 08:36

MOT test number 137652029030

Result ✗ Failed

Fail Horn not working (7.7 (a) (ii))

Fail Nearside Front Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))



MOT #11	2019-10-22 08:20
MOT test number	200202823478
Result	✓ Passed
Advice	Nearside Rear Nail in tyre

MOT #10	2018-10-22 15:31
MOT test number	914386017429
Result	✓ Passed
Advice	Rear of van has been boarded out

MOT #9	2018-10-22 08:48
MOT test number	825372032310
Result	✗ Failed
Fail	Central Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Upper Macpherson strut mounting likely to fail (5.3.3 (b) (ii))
Advice	Rear of van has been boarded out
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a))

MOT #8	2017-10-26 12:41
MOT test number	718029762590
Result	✓ Passed
Advice	Nearside Rear tyre has cut but no cords

**MOT #7** 2017-10-26 08:08**MOT test number** 594061371329**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear tyre has cut but no cords**Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #6** 2016-09-28 14:31**MOT test number** 151074041814**Result** ✓ Passed**Advice** High level stop light not working**MOT #5** 2015-10-28 00:00**MOT test number** 942074248275**Result** ✓ Passed**Advice** High level stop light not working**MOT #4** 2014-10-15 15:16**MOT test number** 555158584260**Result** ✓ Passed

**MOT #3** 2014-10-15 14:44**MOT test number** 598098884261**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nail in nearside rear tyre**MOT #2** 2013-10-07 15:44**MOT test number** 795320883247**Result** ✓ Passed**MOT #1** 2012-10-05 14:44**MOT test number** 669379372240**Result** ✓ Passed**Notice** N/s rear tyre has slight outer sidewall damage



Tax & MOT check

✕
Untaxed

Tax expired:
20 November 2021

✕
MOT

Expired:
2 November 2022

Tax status

Expired at 20 November 2021

Days left

892 days too late

MOT expiry date

2 November 2022

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	REDACTED
Plate since	2019-01-01
Current registration	REDACTED
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	FINANCE
Date of agreement	2024-03-29	2024-03-29
Agreement type	RENAULT	FINANCE
Agreement term	RENAULT	FINANCE
Agreement number	RENAULT	FINANCE
Contact info	RENAULT	FINANCE

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-14
Last registration	2021-11-03
Complete history	See info



Registration #1	2009-10-14	6 mi
Registration #2	2012-10-05	62.722 mi
Registration #3	2013-10-07	74.975 mi
Registration #4	2014-10-15	99.414 mi
Registration #5	2014-10-15	99.414 mi
Registration #6	2015-10-28	116.055 mi
Registration #7	2016-09-28	130.911 mi
Registration #8	2017-10-26	141.958 mi
Registration #9	2018-10-26	152.000 mi
Registration #10	2019-10-26	162.000 mi
Registration #11	2020-10-26	172.000 mi
Registration #12	2021-10-26	182.000 mi
Registration #13	2022-10-26	192.000 mi
Registration #14	2023-10-26	202.000 mi
Registration #15	2024-10-26	212.000 mi
Registration #16	2025-10-26	222.000 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1945 mm
Length	4782 mm
Kerb weight	1678 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	C008646