



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-23
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-28
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	14
Total items failed	12

MOT #17	2023-07-29 09:49
MOT test number	474351258661
Result	✓ Passed
Next expiry date	2024-07-28
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #16	2021-07-02 13:54
MOT test number	819419898359
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))

MOT #15	2020-07-05 10:53
MOT test number	689009152646
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Corrosion present on O/S Sill, not considered excessive at time of mot
Advice	Fluid leak, but not excessive coolant (8.4.1 (a) (i))

**MOT #14** 2019-07-01 09:26**MOT test number** 516546607026**Result** ✓ Passed**MOT #13** 2018-06-29 10:32**MOT test number** 906207289878**Result** ✓ Passed**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive off side rear outer sill (5.3.6 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2018-06-29 10:32**MOT test number** 998190437725**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive off side rear outer sill (5.3.6 (a) (i))**Pass with rectification** Offside Headlamp aim too low and too far to the left. (4.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))**MOT #11** 2017-06-29 12:42**MOT test number** 554450523254**Result** ✓ Passed

**MOT #10** 2017-06-27 13:09**MOT test number** 389094086025**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #9** 2016-06-27 13:54**MOT test number** 564986341066**Result** ✓ Passed**MOT #8** 2015-06-25 13:42**MOT test number** 309466575139**Result** ✓ Passed**MOT #7** 2014-07-04 16:31**MOT test number** 188275484131**Result** ✓ Passed**MOT #6** 2014-07-04 16:31**MOT test number** 497535584156**Result** ✗ Failed**Pass with rectification** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Rear coil spring broken (2.4.C.1a)**MOT #5** 2013-09-25 14:40**MOT test number** 368128063423**Result** ✓ Passed

**MOT #4** 2013-09-25 14:38**MOT test number** 316428463467**Result** ✗ Failed**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2012-09-13 11:35**MOT test number** 996967452258**Result** ✓ Passed**MOT #2** 2012-09-13 11:35**MOT test number** 895227352223**Result** ✗ Failed**Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #1** 2011-09-13 11:28**MOT test number** 507176051251**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
28 July 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		28 July 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXXX
Plate since	2024-03-29
Current registration	 VAUXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-26
Last registration	2023-07-29
Complete history	See info



Registration #1	2008-09-26	16 mi
Registration #2	2011-09-13	44.234 mi
Registration #3	2012-09-13	63.965 mi
Registration #4	2013-09-25	83.823 mi
Registration #5	2013-09-25	83.823 mi
Registration #6	2014-07-04	98.288 mi
Registration #7	2015-06-25	113.976 mi
Registration #8	2016-06-27	128.753 mi
Registration #9	2017-06-27	144.000 mi
Registration #10	2018-06-27	159.247 mi
Registration #11	2019-06-27	174.494 mi
Registration #12	2020-06-27	189.741 mi
Registration #13	2021-06-27	204.988 mi
Registration #14	2022-06-27	220.235 mi
Registration #15	2023-06-27	235.482 mi
Registration #16	2024-06-27	250.729 mi
Registration #17	2025-06-27	265.976 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	2745989