




report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-20
Pictures	26
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #21	2022-07-26 09:55
MOT test number	766870511294
Result	✓ Passed
Next expiry date	2023-08-25
Advice	Brake pipe corroded, covered in grease or other material Front to rears x2 (1.1.11 (c))
Advice	Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #20	2021-08-26 13:24
MOT test number	971923051971
Result	✓ Passed
Advice	Nearside Fuel Pipe/s corroded
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material Both dual lines, front to rear (1.1.11 (c))
Advice	Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Chassis (6.2.2 (d) (i))
Advice	Central Front under body fitted with undertray
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2020-10-19 16:17

MOT test number

644296873054

Result

✓ Passed

- Advice** Undertrays fitted
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))

MOT #18

2020-09-22 15:46

MOT test number

689269257860

Result

✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Engine covers fitted.
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Outer sill. (5.3.6 (a) (i))
- Advice** Both rear suspension coil springs corroded.
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush worn. (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm Inner edge of tread. (5.2.3 (e))
- Advice** Undertrays fitted.
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength lower sill. (5.3.6 (a) (i))

**MOT #17**

2019-09-30 09:48

MOT test number

927773474640

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Fuel Pipe/s corroded
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16

2018-08-17 11:51

MOT test number

619939163638

Result

✓ Passed

- Advice** Rear Fuel Pipe/s corroded
- Advice** Engine bay covers fitted.
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces. (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Undertrays fitted.
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #15

2017-08-16 13:17

MOT test number

890419948071

Result

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #14**

2017-08-15 10:18

MOT test number

740480922804

Result**✗ Failed****Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Outer Brake pipe excessively corroded front to rear (3.6.B.2c)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Inner Brake pipe excessively corroded front to rear (3.6.B.2c)**MOT #13**

2016-08-24 08:01

MOT test number

498230871875

Result**✓ Passed****Advice** Engine covers fitted.**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Undertrays fitted.

**MOT #12**

2016-08-17 12:09

MOT test number

361177246072

Result**✗ Failed**

- Advice** Offside Rear Nail in tyre
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside rear brake excessively fluctuating (3.7.B.3)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Undertrays fitted.
- Fail** Offside Rear Tie bar/rod has excessive play in a ball joint (2.4.G.2)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Mechanical brake component has restricted free movement caliper. (3.5.1k)
- Advice** Engine covers fitted.

MOT #11

2015-08-04 11:46

MOT test number

875396415235

Result**✓ Passed**

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #10** 2014-08-06 10:48**MOT test number** 405018914240**Result** ✓ Passed**MOT #9** 2014-08-06 10:48**MOT test number** 796428614236**Result** ✗ Failed**Pass with rectification** Offside Front Brake hose twisted (3.6.B.4c)**MOT #8** 2013-08-12 09:15**MOT test number** 966314523216**Result** ✓ Passed**Notice** Os flexy slightly twisted**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2013-08-06 10:37**MOT test number** 917588013255**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Os flexy slightly twisted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)


**MOT #6** 2012-09-19 11:22**MOT test number** 258913862222**Result** ✓ Passed**MOT #5** 2012-09-18 15:22**MOT test number** 107092662270**Result** ✗ Failed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Nearside Front front brake juddering severely (3.7.A.2b)**MOT #4** 2011-08-31 10:45**MOT test number** 869983241275**Result** ✓ Passed**Notice** Osf tyre worn inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-05-14 10:39**MOT test number** 694294430160**Result** ✓ Passed**MOT #2** 2009-05-15 16:52**MOT test number** 672515639176**Result** ✓ Passed**MOT #1** 2009-03-25 13:45**MOT test number** 950904889033**Result** ✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	YH06VKU
Plate since	2019-06-28
Current registration	YH06VKU
Plate since	2019-06-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-31
Last registration	2022-07-26
Complete history	See info



Registration #1	2006-03-31	8 mi
Registration #2	2009-03-25	20.960 mi
Registration #3	2009-05-15	22.025 mi
Registration #4	2010-05-14	29.626 mi
Registration #5	2011-08-31	40.015 mi
Registration #6	2012-09-18	48.161 mi
Registration #7	2012-09-19	48.163 mi
Registration #8	2013-08-06	54.604 mi
Registration #9	2013-08-12	54.687 mi
Registration #10	2014-08-06	59.922 mi
Registration #11	2015-08-04	63.317 mi
Registration #12	2016-08-04	66.712 mi
Registration #13	2017-08-04	70.107 mi
Registration #14	2018-08-04	73.502 mi
Registration #15	2019-08-04	76.897 mi
Registration #16	2020-08-04	80.292 mi
Registration #17	2021-08-04	83.687 mi
Registration #18	2022-07-26	87.082 mi
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	060407132209BG