



General information

Make	BMW
Model	640 640D M SPORT
Colour	Black
Year of manufacture	2012
Top speed	155 mph
0 - 60 mph	5.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F





## MOT history

MOT expiry date	2024-10-11
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	42
Total items failed	6

MOT #13 2023-10-06 11:58

MOT test number 107439715373

Result ✓ Passed

Next expiry date 2024-10-11

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm ball joint has slight play front arm (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play front arm (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2022-10-06 15:41

MOT test number 357640070455

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Nail in tyre

**MOT #11**

2022-10-05 09:16

**MOT test number**

160430477947

**Result**

✗ Failed

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-10-08 13:56

**MOT test number**

229896114349

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm ball joint has slight play rear balljoint (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play rear balljoint (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2020-10-12 10:43

**MOT test number**

876239575754

**Result**

✓ Passed

**MOT #8**

2020-01-08 11:07

**MOT test number**

363710868068

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge edge 275/35\*19 (5.2.3 (e))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #7** 2019-04-11 09:48**MOT test number** 724858659244**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #6** 2018-04-16 10:02**MOT test number** 442270184666**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Engine bay/under body covers fitted**MOT #5** 2018-04-03 12:56**MOT test number** 910674608890**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Headlamp cleaning device obviously defective (1.7.2)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Engine bay/under body covers fitted**Fail** Nearside Headlamp cleaning device obviously defective (1.7.2)



MOT #4

2017-03-27 15:02

MOT test number

971109147580

Result

✓ Passed

- Advice

Nearside Front Lower Suspension arm has slight play in a ball joint centre outer (2.4.G.2)
- Advice

Nearside Front Lower Suspension arm has slight play in a pin/bush front outer (2.4.G.2)
- Advice

Wiper blades on limit of effectiveness
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front Lower Suspension arm has slight play in a ball joint centre outer (2.4.G.2)
- Advice

Full inspection of under body and under bonnet components not possible, covers fitted
- Advice

Offside Front Lower Suspension arm has slight play in a pin/bush front outer (2.4.G.2)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3**

2017-03-27 09:41

**MOT test number**

407606230974

**Result****✗ Failed**

- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Advice** Wiper blades on limit of effectiveness
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint centre outer (2.4.G.2)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush front outer (2.4.G.2)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Full inspection of under body and under bonnet components not possible, covers fitted
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint centre outer (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush front outer (2.4.G.2)

**MOT #2**

2016-04-01 13:30

**MOT test number**

549884230735

**Result****✓ Passed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Full inspection of under body and under bonnet components not possible, covers fitted.

**MOT #1**

2015-03-06 15:29

**MOT test number**

128105965012

**Result****✓ Passed**



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
11 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	11 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-07
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2012-03-07	14 mi
Registration #2	2015-03-06	34.370 mi
Registration #3	2016-04-01	48.539 mi
Registration #4	2017-03-27	61.511 mi
Registration #5	2017-03-27	61.511 mi
Registration #6	2018-04-03	67.280 mi
Registration #7	2018-04-16	67.309 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	83%
Pedestrian	78%
Safety systems	100%
Overall rating	90%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1894 mm
Height	1369 mm
Length	4894 mm
Wheel base	2855 mm
Kerb weight	1715 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	35237989