




report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Red
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-09
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	24
Total items failed	16

MOT #18	2023-07-27 11:10
MOT test number	787345620767
Result	✓ Passed
Next expiry date	2024-07-26

MOT #17	2022-10-14 09:58
MOT test number	327180667718
Result	✓ Passed

MOT #16	2021-10-14 12:01
MOT test number	328143533972
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Sills corroded not considered excessive



MOT #15

2021-09-21 14:02

MOT test number

973046034057

Result		✗ Failed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Non obligatory mirror damaged	
Fail	Offside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))	
Fail	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))	
Advice	Front Tyre worn close to legal limit/worn on edge both tyres (5.2.3 (e))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Fail	Nearside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))	
Fail	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))	

**MOT #14**

2021-07-27 09:13

MOT test number

217243107344

Result

✗ Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Non obligatory mirror damaged**Fail** Nearside Rear Suspension arm corroded and seriously weakened at spring (5.3.3 (b) (i))**Fail** Emissions not tested low fuel (8.2.2.2 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Suspension arm corroded and seriously weakened at spring (5.3.3 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**MOT #13**

2020-06-19 11:39

MOT test number

281708319676

Result

✓ Passed

MOT #12

2020-06-19 08:07

MOT test number

172550459967

Result

✗ Failed

Fail Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**Fail** Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #11** 2019-07-31 15:11**MOT test number** 451445437560**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2018-06-01 07:48**MOT test number** 535996653614**Result** ✓ Passed**MOT #9** 2017-06-02 09:24**MOT test number** 217562635407**Result** ✓ Passed**MOT #8** 2016-05-06 07:58**MOT test number** 924632439271**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Both front tyres wearing thin on the edges**MOT #7** 2015-05-07 14:19**MOT test number** 377147825109**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #6** 2015-05-06 16:16**MOT test number** 795656625175**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2014-05-13 13:00**MOT test number** 927143334167**Result** ✓ Passed**MOT #4** 2014-05-12 16:48**MOT test number** 606162434116**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #3** 2013-05-16 08:45**MOT test number** 617926633140**Result** ✓ Passed**MOT #2** 2012-04-24 11:21**MOT test number** 267685312158**Result** ✓ Passed**MOT #1** 2011-04-18 11:25**MOT test number** 365758201166**Result** ✓ Passed**Notice** Undertray fitted engine and sills not allowing full inspection



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-08
Last registration	2023-07-27
Complete history	See info



Registration #1	2008-05-08	27 mi
Registration #2	2011-04-18	21.131 mi
Registration #3	2012-04-24	28.006 mi
Registration #4	2013-05-16	37.134 mi
Registration #5	2014-05-12	42.986 mi
Registration #6	2014-05-13	42.986 mi
Registration #7	2015-05-06	48.053 mi
Registration #8	2015-05-07	48.054 mi
Registration #9	2016-05-06	54.787 mi
Registration #10	2017-06-02	61.198 mi
Registration #11	2018-05-20	65.277 mi
Registration #12	2019-05-20	70.277 mi
Registration #13	2020-05-20	75.277 mi
Registration #14	2021-05-20	80.277 mi
Registration #15	2022-05-20	85.277 mi
Registration #16	2023-05-20	90.277 mi
Registration #17	2024-05-20	95.277 mi
Registration #18	2025-05-20	100.277 mi
Registration #19	2026-05-20	105.277 mi
Registration #20	2027-05-20	110.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG