



VEI3NJ0

report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | AUDI |
| Model | A4 TDI SE TECHNIK |
| Colour | Black |
| Year of manufacture | 2013 |
| Top speed | 140 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 161 BHP |
| Max. torque | 380 Nm at 2.500 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 115 g/km |
| CO2 label | C |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-08-18 |
| Pictures | 48 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-24 |
| Pictures | 1 |
| Listing price | View report |



source: [cargurus.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-02 |
| MOT pass rate | 89 % |
| MOT passed | 8 |
| Failed MOT tests | 1 |
| Total advice items | 25 |
| Total items failed | 1 |

| | |
|------------------|---------------------------------------------------------------------------------------|
| MOT #9 | 2023-08-03 12:38 |
| MOT test number | 879921812645 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-02 |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 225/50r17 (5.2.3 (e)) |

**MOT #8**

2023-08-03 08:00

MOT test number

826794577089

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 225/50r17 (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7

2022-06-25 10:16

MOT test number

657229504624

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

2021-07-08 08:55

MOT test number

382945398243

Result**✓ Passed**

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #5** 2020-07-14 15:42**MOT test number** 442624804888**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2019-07-13 08:32**MOT test number** 547708072299**Result** ✓ Passed**MOT #3** 2018-07-18 09:38**MOT test number** 297343278386**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust clamp corroded**MOT #2** 2017-07-03 09:44**MOT test number** 421794273162**Result** ✓ Passed**Advice** Tyres tread low front tyres worn inner edges**MOT #1** 2016-07-01 13:24**MOT test number** 273581663814**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 2 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this AUDI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2013-07-20 |
| Last registration | 2023-08-03 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2013-07-20 | 26 mi |
| Registration #2 | 2016-07-01 | 29.492 mi |
| Registration #3 | 2017-07-03 | 45.012 mi |
| Registration #4 | 2018-07-18 | 59.135 mi |
| Registration #5 | 2019-07-13 | 71.555 mi |
| Registration #6 | 2020-07-14 | 82.885 mi |
| Registration #7 | 2021-07-14 | 95.277 mi |
| Registration #8 | 2022-07-14 | 107.669 mi |
| Registration #9 | 2023-07-14 | 120.061 mi |
| Registration #10 | 2024-07-14 | 132.453 mi |
| Registration #11 | 2025-07-14 | 144.845 mi |
| Registration #12 | 2026-07-14 | 157.237 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 93% |
| Children | 84% |
| Pedestrian | 39% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2040 mm |
| Height | 1427 mm |
| Length | 4701 mm |
| Wheel base | 2808 mm |
| Kerb weight | 1475 kg |
| Max. allowed weight | 2025 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 63 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | CGLD286635 |