



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R
Colour	Grey
Year of manufacture	-
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-24
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT #17

2021-07-16 08:51

MOT test number

267745631072

Result

✗ Failed

Advice Front Brake pad(s) wearing thin BOTH FRONTS (1.1.13 (a) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Nail in tyre**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Front Headlamp lens slightly defective BOTH FRONTS (4.1.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Has a nail (5.2.3 (e))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #16

2020-07-01 11:15

MOT test number

937244098532

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material as marked (1.1.11 (c))**Advice** Nearside Front fog lamp not working**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material as marked (1.1.11 (c))

**MOT #15**

2019-07-05 13:32

MOT test number

205971640934

Result

✓ Passed

- Advice** Rear inner sills corroding
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users on acceleration (8.2.2.2 (c))
- Advice** Items removed from driver's view prior to test
- Advice** Luggage in o/s rear seats and thus seat belts not checked

MOT #14

2019-07-04 11:54

MOT test number

968122461364

Result

✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Rear inner sills corroding
- Fail** Nearside Headlamp lens seriously defective no beam pattern (4.1.1 (b) (ii))
- Advice** Luggage in o/s rear seats and thus seat belts not checked
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users on acceleration (8.2.2.2 (c))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #13

2018-07-10 10:03

MOT test number

730481211207

Result

✓ Passed

**MOT #12**

2017-07-11 09:05

MOT test number

742740992770

Result

✓ Passed

Advice Nearside Front Brake disc slight scored**Advice** Front wiper blade worn**MOT #11**

2016-07-15 14:19

MOT test number

883809393485

Result

✓ Passed

Advice Items removed from driver's view prior to test**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**MOT #10**

2016-07-15 08:32

MOT test number

280924480117

Result

✗ Failed

Advice Items removed from driver's view prior to test**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**MOT #9**

2015-07-16 14:17

MOT test number

477647995196

Result

✓ Passed

**MOT #8** 2015-07-15 11:33**MOT test number** 985756395157**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2014-07-30 14:45**MOT test number** 756781714220**Result** ✓ Passed**MOT #6** 2013-07-31 15:17**MOT test number** 836192013207**Result** ✓ Passed**Advice** Exhaust emits black smoke during acceleration (7.3.A.2c)**MOT #5** 2013-07-31 13:36**MOT test number** 475312413253**Result** ✗ Failed**Advice** Exhaust emits black smoke during acceleration (7.3.A.2c)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #4** 2012-07-05 13:39**MOT test number** 769387582177**Result** ✓ Passed



MOT #3	2011-07-28 16:32
MOT test number	217799601277
Result	✓ Passed
MOT #2	2010-07-29 14:19
MOT test number	651310610243
Result	✓ Passed
MOT #1	2009-08-01 12:27
MOT test number	514833219255
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	WV55NXB
Plate since	2019-03-29
Current registration	WV55NXB
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-09-02
Last registration	2021-07-16
Complete history	See info



Registration #1	2005-09-02	14 mi
Registration #2	2009-08-01	37.696 mi
Registration #3	2010-07-29	52.471 mi
Registration #4	2011-07-28	69.043 mi
Registration #5	2012-07-05	76.597 mi
Registration #6	2013-07-31	82.295 mi
Registration #7	2013-07-31	82.295 mi
Registration #8	2014-07-30	93.024 mi
Registration #9	2015-07-15	105.838 mi
Registration #10	2015-07-16	105.838 mi
Registration #11	2016-07-15	117.577 mi
Registration #12	2017-07-15	129.316 mi
Registration #13	2018-07-15	141.055 mi
Registration #14	2019-07-15	152.794 mi
Registration #15	2020-07-15	164.533 mi
Registration #16	2021-07-15	176.272 mi
Registration #17	2022-07-15	188.011 mi
Registration #18	2023-07-15	199.750 mi
Registration #19	2024-03-29	211.489 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1CD0528926