




report date: 2024-03-29

General information

Make	CITROEN
Model	C2 HDI RHYTHM
Colour	Black
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 2


Date	2021-10-30
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-28
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	22
Total items failed	6

MOT #16 2023-09-15 17:54

MOT test number 892051877591

Result ✓ Passed

Next expiry date 2024-09-17

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15 2023-09-15 17:54

MOT test number 262609786888

Result ✗ Failed

- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2022-09-16 12:36**MOT test number** 207418975980**Result** ✓ Passed

- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2021-09-09 09:02**MOT test number** 501008632470**Result** ✓ Passed**MOT #12** 2020-09-18 09:02**MOT test number** 790047619935**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2019-11-20 14:59**MOT test number** 767992876715**Result** ✓ Passed**MOT #10** 2019-11-20 12:30**MOT test number** 542033899476**Result** ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2018-11-23 09:15**MOT test number** 338922694064**Result** ✓ Passed**MOT #8** 2018-01-15 12:02**MOT test number** 581408410522**Result** ✓ Passed**Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #7** 2017-01-17 09:23**MOT test number** 709824549444**Result** ✓ Passed**MOT #6** 2016-01-08 11:55**MOT test number** 836948212955**Result** ✓ Passed**MOT #5** 2016-01-08 09:42**MOT test number** 822698651980**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #4** 2015-01-19 11:53**MOT test number** 805509715060**Result** ✓ Passed

**MOT #3** 2014-01-24 14:35**MOT test number** 755264324093**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-08-22 12:56**MOT test number** 379755132257**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-08-22 12:56**MOT test number** 555885632265**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
27 April 2024

✓

MOT

Expires:
17 September 2024

Tax status	Expired at 27 April 2024
Days left	2 days too late
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-23
Last registration	2023-09-15
Complete history	See info



Registration #1	2009-09-23	29 mi
Registration #2	2012-08-22	21.557 mi
Registration #3	2014-01-24	34.227 mi
Registration #4	2015-01-19	44.750 mi
Registration #5	2016-01-08	54.428 mi
Registration #6	2016-01-08	54.428 mi
Registration #7	2017-01-17	63.021 mi
Registration #8	2018-01-15	72.885 mi
Registration #9	2018-11-23	79.670 mi
Registration #10	2019-05-29	85.377 mi
Registration #11	2019-05-29	85.377 mi
Registration #12	2019-05-29	85.377 mi
Registration #13	2019-05-29	85.377 mi
Registration #14	2019-05-29	85.377 mi
Registration #15	2019-05-29	85.377 mi
Registration #16	2019-05-29	85.377 mi
Registration #17	2019-05-29	85.377 mi
Registration #18	2019-05-29	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1003 kg
Max. allowed weight	1391 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FDAM2216669