



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Purple
Year of manufacture	2005
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-03-01
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-27
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-03
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	19
Total items failed	9

MOT #22	2024-01-04 13:09
MOT test number	831765017345
Result	✓ Passed
Next expiry date	2025-01-03

MOT #21	2023-12-19 16:33
MOT test number	220604331221
Result	✗ Failed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Rear Exhaust system insecure (6.1.2 (a))

MOT #20	2022-09-26 15:47
MOT test number	132969395539
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19** 2022-09-21 11:44**MOT test number** 966904552123**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2021-09-08 11:46**MOT test number** 131940620499**Result** ✓ Passed**Advice** Slight corrosion to underside of vehicle**MOT #17** 2021-09-08 11:46**MOT test number** 637754153555**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Pass with rectification** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Slight corrosion to underside of vehicle**MOT #16** 2020-09-08 13:39**MOT test number** 693908680278**Result** ✓ Passed**MOT #15** 2020-09-08 11:52**MOT test number** 936389099374**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #14** 2019-09-12 10:53**MOT test number** 465613665930**Result** ✓ Passed**MOT #13** 2018-09-21 14:49**MOT test number** 904842507773**Result** ✓ Passed**Advice** Offside Front Power steering component has slight seepage from a component rack (2.1.5 (a))**MOT #12** 2017-09-21 11:10**MOT test number** 854921790212**Result** ✓ Passed**Advice** Central Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #11** 2016-09-27 14:16**MOT test number** 288176170523**Result** ✓ Passed**MOT #10** 2016-03-31 10:48**MOT test number** 612935923806**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nail in n/s/r tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-03-23 11:57**MOT test number** 805242585045**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-03-13 10:14**MOT test number** 856222374089**Result** ✓ Passed**MOT #7** 2014-03-13 10:14**MOT test number** 997552774032**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-03-28 12:08**MOT test number** 438917383064**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-03-16 11:52**MOT test number** 158036072079**Result** ✓ Passed**MOT #4** 2011-03-28 12:09**MOT test number** 139727781014**Result** ✓ Passed



MOT #3	2010-04-07 12:07
MOT test number	681387990054
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2009-04-08 15:09
MOT test number	210038499082
Result	✓ Passed

MOT #1	2008-02-28 11:54
MOT test number	963889958067
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	CV05RRO
Plate since	2019-03-29
Current registration	CV05RRO
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-01
Last registration	2024-01-04
Complete history	See info



Registration #1	2005-03-01	25 mi
Registration #2	2008-02-28	17.834 mi
Registration #3	2010-04-07	26.503 mi
Registration #4	2011-03-28	36.203 mi
Registration #5	2012-03-16	47.555 mi
Registration #6	2013-03-28	55.304 mi
Registration #7	2014-03-13	63.245 mi
Registration #8	2015-03-23	67.133 mi
Registration #9	2016-03-31	72.717 mi
Registration #10	2016-09-27	76.133 mi
Registration #11	2017-09-21	80.851 mi
Registration #12	2018-09-21	84.063 mi
Registration #13	2019-09-21	87.275 mi
Registration #14	2020-09-21	90.487 mi
Registration #15	2021-09-21	93.699 mi
Registration #16	2022-09-21	96.911 mi
Registration #17	2023-09-21	100.123 mi
Registration #18	2024-01-04	103.335 mi
Registration #19	2024-01-04	106.547 mi
Registration #20	2024-01-04	109.759 mi
Registration #21	2024-01-04	112.971 mi
Registration #22	2024-01-04	116.183 mi
Registration #23	2024-01-04	119.395 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	12922