



**KW63MSO**

report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	White
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-08-08
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #11 2023-08-02 14:29

MOT test number 999559421515

Result ✓ Passed

Next expiry date 2024-08-07

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice** Rear Exhaust has a minor leak of exhaust gases outer skins deteriorated (6.1.2 (a))

MOT #10 2022-08-08 13:39

MOT test number 871899395890

Result ✓ Passed

MOT #9 2022-01-28 15:46

MOT test number 132700615920

Result ✓ Passed

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Offside Front Play in steering rack inner joint(s)

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn heavily on edges (5.2.3 (e))

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2022-01-28 09:18**MOT test number** 618491069534**Result** ✗ Failed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Tyre has ply or cords exposed 185/65/15 (5.2.3 (d) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn heavily on edges (5.2.3 (e))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Front Windscreen wiper does not clear the windscreen effectively Both front blades (3.4 (b) (ii))**MOT #7** 2021-01-28 11:37**MOT test number** 126938619133**Result** ✓ Passed**MOT #6** 2021-01-28 09:06**MOT test number** 260991146235**Result** ✗ Failed**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #5** 2020-01-29 16:24**MOT test number** 932311117628**Result** ✓ Passed

**MOT #4** 2020-01-28 15:23**MOT test number** 119031437010**Result** ✗ Failed**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #3** 2019-02-01 09:48**MOT test number** 418464794155**Result** ✓ Passed**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #2** 2018-01-31 17:21**MOT test number** 118011344906**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2017-02-01 11:44**MOT test number** 317096628431**Result** ✓ Passed**Advice** O/s/r parking brake slightly lazy



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
7 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	7 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-02-01
Last registration	2023-08-02
Complete history	<a href="#">See info</a>



Registration #1	2014-02-01	12 mi
Registration #2	2017-02-01	26.228 mi
Registration #3	2018-01-31	31.833 mi
Registration #4	2019-02-01	37.316 mi
Registration #5	2020-01-28	42.513 mi
Registration #6	2020-01-29	42.513 mi
Registration #7	2021-01-28	44.796 mi
Registration #8	2022-01-28	46.277 mi
Registration #9	2022-01-28	46.277 mi
Registration #10	2022-01-28	46.277 mi
Registration #11	2022-01-28	46.277 mi
Registration #12	2022-01-28	46.277 mi
Registration #13	2023-08-02	48.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	0798077