





report date: 2024-03-29

#### General information

Make	MINI
Model	PACEMAN COOPER D
Colour	Grey
Year of manufacture	2014
Top speed	116 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

#### Internet history

#### Entry 1

Date 2022-03-31

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2024-08-30
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	5

MOT #9	2023-08-31 15:15
MOT test number	263589202207
Result	✓ Passed
Next expiry date	2024-08-30

мот	#8	2023-08-31 09:16
МОТ	test number	820097172097
Resu	ilt	<b>X</b> Failed
Fai	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fai	Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	

MOT #7	2022-11-29 14:27
MOT test number	877083843404
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #6		2021-11-26 16:04
MOT test	number	985438734728
Result		✓ Passed
Advice	Stone chip front screen	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #5** 2021-11-26 09:56

MOT test number 325050032471

Result X Failed

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Stone chip front screen

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning outer sidelight not working (4.2.1 (a) (i))

**Fail** Nearside Rear Inner Tyre has ply or cords exposed edge of treads and cracking up outer sidewall (5.2.3 (d) (ii))

Fail Front Headlamp aim too high offside and nearside (4.1.2 (a))

Advice Offside Front tyre just started to crack up inbetween treads

**MOT #4** 2020-11-26 12:42

**MOT test number** 990257103958

**Result** ✓ Passed

MOT #3 2019-11-25 09:16

MOT test number 816752971301

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front tyre starting to wear on outer edge and small cuts on tread

MOT #2 2018-12-01 10:04

**MOT test number** 737232356174

Result \rightarrow Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Plastic covers underside fitted

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-11-21 09:27

**MOT test number** 543811458704

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\sim$			
Own	or h	1St	าrv
	וו וט	IJU	יוע

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a> .		
***************************************		
***************************************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-12-18
Last registration	2023-08-31
Complete history	See info



Registration #1	2014-12-18	23 mi
Registration #2	2017-11-21	27.318 mi
Registration #3	2018-12-01	35.335 mi
Registration #4	2019-11-25	42.287 mi
Registration #5	2020-11-26	47.385 mi
Registration #6	2021-11-26	54.487 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 ea
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1996 mm
Height	1518 mm
Length	4109 mm
Wheel base	2596 mm
Max. allowed weight	1770 kg

# Additional information

Fuel tank capacity	47 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 12/12

**Engine number** 

71569063