





report date: 2024-03-29

General information

| Make | AUDI |
|---------------------|------------------------|
| Model | S3 S3 TFSI QUATTRO |
| Colour | Blue |
| Year of manufacture | 2009 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.5 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| Power | 265 BHP |
|-------------------------|---------------------|
| Max. torque | 350 Nm at 5.000 rpm |
| Engine capacity | 1.984 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.5 mpg |
| Consumption extra urban | 42.2 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 198 g/km |
| CO2 label | J |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-02-16

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



| | \sim $-$ | |
|---|------------|---------|
| M | () | history |
| | | |

| MOT expiry date | 2025-02-21 |
|--------------------|------------|
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 5 |

| MOT #15 | 2024-02-22 16:39 |
|------------------|------------------|
| MOT test number | 493564966941 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-21 |

| MOT #14 | 2023-02-01 15:12 |
|-----------------|------------------|
| MOT test number | 801977911465 |
| Result | ✓ Passed |

| MOT #13 | 2022-02-21 13:08 |
|-----------------|------------------|
| MOT test number | 235688559827 |
| Result | ✓ Passed |

| MOT #12 | 2021-05-25 10:37 |
|---------|------------------|

MOT test number 576031707646

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #11 2021-05-21 07:42

MOT test number 914368694389

Result X Failed

Fail Front Exhaust system insecure (6.1.2 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Fail Front Brake disc in such a condition that it is seriously weakened both (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2019-11-12 11:33

MOT test number 114744754807

Result

Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9 2019-11-07 10:06

MOT test number 574518010883

Result X Failed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #8 2018-11-16 10:39

MOT test number 175028127881

Advice Small exhaust leak

CarCheck.co.uk page 4/12



MOT #7 2017-11-20 13:48

MOT test number 133872681177

Result ✓ Passed

MOT #6 2016-11-23 11:52

MOT test number 476494610964

Result ✓ Passed

MOT #5 2015-11-20 12:14

MOT test number 832023073622

Result \(\sqrt{Passed} \)

MOT #4 2014-11-03 12:19

MOT test number 569477404330

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2013-11-01 08:13

MOT test number 468724903342

Result ✓ Passed

MOT #2 2013-08-30 08:45

MOT test number 546232543273

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-08-27 14:08

MOT test number 756140442218

Result

Passed

CarCheck.co.uk page 5/12





Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 21 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I | |
|--|-------------|
| | |
| THE STATE OF THE S | |
| *************************************** | |
| *************************************** | |
| | |
| THE PARTY OF THE P | |
| *************************************** | |
| ************* | |
| | More info > |
| | 110100 |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| | |
| Number of plates | , |
| Current registration | NK SIE |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2009-09-01 |
| Last registration | 2024-02-22 |
| Complete history | See info |



| Registration #1 | 2009-09-01 | 7 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-08-27 | 33.224 mi |
| Registration #3 | 2013-08-30 | 44.943 mi |
| Registration #4 | 2013-11-01 | 46.895 mi |
| Registration #5 | 2014-11-03 | 54.630 mi |
| Registration #6 | 2015-11-20 | 60.959 mi |
| Registration #7 | 2016-11-23 | 65.460 mi |
| Registration #8 | 2017-11-20 | 68.934 mi |
| Registration #9 | 2018-11-16 | 73.547 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.77 66 |
| Registration #14 | | 11.777 es |
| Registration #15 | | 9.77 66 |
| Registration #16 | | 0.00 44 |
| Registration #17 | | 11,777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|---------------------|---------|
| Height | 1399 mm |
| Length | 4230 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1455 kg |
| Max. allowed weight | 2015 kg |

Additional information

| Fuel tank capacity | 60 I | |
|-----------------------------------|------------------|-------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 5 page 1 | 12/12 |

Number of axles 2

Engine number CDL 019426