





report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE 16V
Colour	Red
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	127 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

MOT history

MOT #15	2020-11-18 09:00
MOT test number	753033119112
Result	√ Passed
Next expiry date	2021-12-03

MOT #14	2019-12-04 15:00
MOT test number	863154103418
Result	✓ Passed

MOT #13 2018-10-18 15:30 **MOT test number** 978766483936 Result ✓ Passed Offside Rear Road wheel slightly distorted (5.2.2 (c) (i)) Advice **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2018-10-18 09:38
MOT test number	340759615275
Result	X Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #11	2017-10-05 12:20
MOT test number	395202115587
Result	✓ Passed
Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT test number

Fail Nearside Stop lamp not working (1.2.1b)

2017-10-05 09:18

500543328761

X Failed

X Failed

Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #9

MOT test number

567932605364

Result

Advice Nearside Rear Nail in tyre

MOT test number
674764227397

Result
Advice Nearside Rear Nail in tyre

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #7

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number
943683346369

Result

Fail Nearside Front coil spring broken (2.4.C.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front coil spring broken (2.4.C.1a)

Nearside Registration plate lamp not working (1.1.C.1d)

MOT #5

MOT test number

Result

Notice Play in steering rack inner joint(s)

2014-09-29 10:52

287092274210

V Passed


MOT #4 2014-09-19 10:34 316812164246 **MOT** test number Result × Failed Nearside Headlamp aim too high (1.8) Fail **Notice** Play in steering rack inner joint(s) Fail Nearside Front coil spring broken (2.4.C.1a) Fail Offside Track rod end ball joint has excessive play (2.2.B.1f) Fail Offside Headlamp aim too high (1.8) Fail Offside Stop lamp not working (1.2.1b) Fail Offside Front coil spring broken (2.4.C.1a)

MOT #3	2013-08-02 12:16
MOT test number	229324213259
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29



MOT #1	2010-07-01 11:40
MOT test number	661372480133
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	OK SIE
Plate since	
	Moro info

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-06-27
Last registration	2020-11-18
Complete history	See info



Registration #1	2007-06-27	13 mi
Registration #2	2010-07-01	22.168 mi
Registration #3	2012-02-06	34.215 mi
Registration #4	2013-08-02	38.170 mi
Registration #5	2014-09-19	38.966 mi
Registration #6	2014-09-29	38.966 mi
Registration #7	2015-09-14	41.802 mi
Registration #8	2015-09-14	41.805 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1496 mm
Length	3986 mm
Wheel base	2575 mm
Kerb weight	1135 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/1: