




report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Silver
Year of manufacture	2006
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-06-12
Pictures	4
Listing price	<a href="#">View report</a>



source: yesauto.com

**MOT history**

<b>MOT expiry date</b>	2024-03-06
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	32
<b>Total items failed</b>	7

**MOT #20** 2023-03-07 10:51**MOT test number** 780641923907**Result** Passed**Next expiry date** 2024-03-06

- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #19** 2022-02-15 11:55**MOT test number** 675067215436**Result** Passed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #18** 2021-03-17 12:34**MOT test number** 254332059634**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, but not excessively Both sides (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #17** 2020-03-19 09:16**MOT test number** 855640649269**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16** 2019-03-15 11:11**MOT test number** 548117958468**Result** ✓ Passed**Advice** Engine covers fitted obscuring some components**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Surface corrosion underneath on some components**Advice** Front tyres starting to perish inbetween treads**MOT #15** 2018-03-05 15:55**MOT test number** 972213462435**Result** ✓ Passed

**MOT #14** 2018-03-05 11:45**MOT test number** 137387714461**Result** ✗ Failed**Fail** Central Upper Stop lamp not working (1.2.1b)**MOT #13** 2017-03-13 13:03**MOT test number** 947164779554**Result** ✓ Passed**Advice** Engine cover fitted obscuring some components**Advice** Windscreen has damage in nearside bottom corner**MOT #12** 2017-03-13 09:53**MOT test number** 504722434878**Result** ✗ Failed**Advice** Windscreen has damage in nearside bottom corner**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Engine cover fitted obscuring some components**MOT #11** 2016-03-09 16:57**MOT test number** 102704988959**Result** ✓ Passed**MOT #10** 2015-03-12 16:44**MOT test number** 249001475000**Result** ✓ Passed**Notice** 3 bulbs not workink in high level stop light**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #9** 2014-02-22 08:20**MOT test number** 106643854487**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-02-21 10:51**MOT test number** 986442454002**Result** ✗ Failed**Fail** Bootlid cannot be secured in the closed position (6.4.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-03-19 12:15**MOT test number** 347518273033**Result** ✓ Passed**MOT #6** 2012-03-16 13:21**MOT test number** 628406972051**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-03-21 14:29**MOT test number** 627420781074**Result** ✓ Passed

**MOT #4** 2011-03-21 14:29**MOT test number** 178830281466**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #3** 2010-01-30 10:49**MOT test number** 190990230081**Result** ✓ Passed**MOT #2** 2010-01-30 10:49**MOT test number** 253200530042**Result** ✗ Failed**Pass with rectification** Centre Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**MOT #1** 2009-01-17 11:04**MOT test number** 960577519098**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✗  
**MOT**  
  
Expired:  
6 March 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	6 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	HV55VJN
Plate since	2024-03-29
Current registration	HV55VJN
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-01-31
Last registration	2023-03-07
Complete history	<a href="#">See info</a>



Registration #1	2006-01-31	10 mi
Registration #2	2009-01-17	17.737 mi
Registration #3	2010-01-30	22.486 mi
Registration #4	2011-03-21	26.249 mi
Registration #5	2012-03-16	29.630 mi
Registration #6	2013-03-19	33.569 mi
Registration #7	2014-02-21	37.377 mi
Registration #8	2014-02-22	37.378 mi
Registration #9	2015-03-12	41.258 mi
Registration #10	2016-03-09	43.817 mi
Registration #11	2016-03-09	43.817 mi
Registration #12	2016-03-09	43.817 mi
Registration #13	2016-03-09	43.817 mi
Registration #14	2016-03-09	43.817 mi
Registration #15	2016-03-09	43.817 mi
Registration #16	2016-03-09	43.817 mi
Registration #17	2016-03-09	43.817 mi
Registration #18	2016-03-09	43.817 mi
Registration #19	2016-03-09	43.817 mi
Registration #20	2016-03-09	43.817 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 051011