





report date: 2024-03-29

## General information

Make	BMW
Model	125 125I SE
Colour	Black
Year of manufacture	2008
Top speed	148 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	218 BHP
Max. torque	270 Nm at 4.250 rpm
Engine capacity	2.996 сс
Cylinders	6
Fuel type	Petrol
Consumption city	24.1 mpg
Consumption extra urban	47.1 mpg
Consumption combined	34.9 mpg
CO2 emission	195 g/km
CO2 label	1



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

## Entry 2

Date 2021-07-16

Pictures 41

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-14
Pictures	41

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



DN08RVR report date: 2024-03-29

MOT history

MOT expiry date	2025-01-12
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	18
Total items failed	4

MOT #18		2024-01-13 11:08
MOT test	number	509863043783
Result		✓ Passed
Next expi	y date	2025-01-12
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17		2022-10-25 14:52
MOT test n	umber	162439980949
Result		✓ Passed
MOT #16		2021-10-15 15:01
MOT test n	umber	951285747460
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/13



**Advice** 

**DN08RVR** 

report date: 2024-03-29

MOT test number

S11175245874

Result

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (iii))

 MOT #14
 2019-08-12 08:28

 MOT test number
 693967433842

 Result
 ✓ Passed

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

MOT test number

802250454655

Result

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #12

MOT test number

230786235172

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge low tread 215/40y18 (5.2.3 (e))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Oil leak

Advice Engine covers fitted obscuring some components in the engine bay

Advice Under-trays fitted obscuring some underside components

MOT test number
942240579374

Result

Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)

Advice Engine covers fitted obscuring some components in the engine bay

Advice Oil leak

Advice Under-trays fitted obscuring some underside components

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8

MOT test number

496239915208

Result

Notice Nearside front tyre wearing on inner edges

CarCheck.co.uk page 5/13



report date: 2024-03-29

**MOT test number** 208420124207

MOT #6 2014-04-03 08:23

**MOT test number** 586413394001

Result 

Passed

MOT #5 2014-04-02 17:06

**MOT test number** 677082594099

**Result** X Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #4 2013-03-22 16:01

**MOT test number** 587371383052

MOT #3 2012-03-27 09:45

MOT test number 427727382084

**Result** ✓ Passed

MOT #2 2012-03-26 12:05

**MOT test number** 647096582005

**Result** X Failed

**Fail** Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1 2011-04-29 12:51

**MOT test number** 418909111154

CarCheck.co.uk page 6/13



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	12 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

## Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		/e?
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	UK C	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-06-10
Last registration	2024-01-13
Complete history	See info



Registration #1	2008-06-10	22 mi
Registration #2	2011-04-29	34.581 mi
Registration #3	2012-03-26	49.382 mi
Registration #4	2012-03-27	49.382 mi
Registration #5	2013-03-22	63.579 mi
Registration #6	2014-04-02	71.831 mi
Registration #7	2014-04-03	71.831 mi
Registration #8	2014-08-08	71.838 mi
Registration #9	2015-08-07	78.416 mi
Registration #10	2016-07-29	99.002 mi
Registration #11	2017-08-07	118.979 mi
Registration #12		77.777 es
Registration #13		71.777 es
Registration #14		77.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1748 mm
Height	1411 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1510 kg
Max. allowed weight	1950 kg

# Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4	page 13/13