



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Blue
Year of manufacture	-
Top speed	86 mph
0 - 60 mph	18.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	62 BHP
Max. torque	98 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1	
Date	2021-10-19
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #19**

2022-10-12 14:13

**MOT test number**

613149840189

**Result****✗ Failed**

- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Fail** Offside Front Sub-frame corroded and seriously weakened Around anti-roll bar mounting point (5.3.3 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2021-10-18 11:22

**MOT test number**

620178858939

**Result****✓ Passed**

- Minor** Offside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush in poor condition. Borderline. (5.3.4 (a) (i))

**MOT #17**

2021-10-09 07:42

**MOT test number**

267040626973

**Result****✗ Failed**

- Fail** Offside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Fail** Offside Rear Suspension arm corroded and seriously weakened bush (5.3.3 (b) (i))

**MOT #16**

2020-10-16 15:12

**MOT test number**

447278867393

**Result**

✓ Passed

**Advice** Offside Rear Suspension arm corroded but not seriously weakened trailing arm (5.3.3 (b) (i))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arms bushes both sides (5.3.4 (a) (i))**MOT #15**

2020-10-10 07:59

**MOT test number**

739336406043

**Result**

✗ Failed

**Advice** Offside Rear Suspension arm corroded but not seriously weakened trailing arm (5.3.3 (b) (i))**Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Exhaust has a major leak of exhaust gases back box and centre pipe (6.1.2 (a))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arms bushes both sides (5.3.4 (a) (i))**Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #14**

2019-10-05 06:52

**MOT test number**

914028176594

**Result**

✓ Passed

**Advice** Offside Rear Suspension arm corroded but not seriously weakened trailing arm to bush (5.3.3 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #13** 2018-10-13 10:38**MOT test number** 230074926065**Result** ✓ Passed**Advice** Offside Rear Suspension arm corroded but not seriously weakened trailing arm to bush (5.3.3 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #12** 2017-10-14 07:52**MOT test number** 204229266960**Result** ✓ Passed**Advice** Nearside Lower Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Front Exhaust has a minor leak of exhaust gases flexie (7.1.2)**Advice** Brake pedal anti-slip provision worn**MOT #11** 2016-10-08 10:32**MOT test number** 180693995109**Result** ✓ Passed**MOT #10** 2015-10-13 13:28**MOT test number** 142178554380**Result** ✓ Passed**MOT #9** 2015-10-12 08:41**MOT test number** 959161493966**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**MOT #8** 2014-10-09 16:03**MOT test number** 236712184228**Result** ✓ Passed**MOT #7** 2013-10-15 11:07**MOT test number** 747798583237**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-10-15 11:07**MOT test number** 409058083201**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-10-17 10:48**MOT test number** 879221792270**Result** ✓ Passed**Notice** O/s/r tyre has signs of perishing**MOT #4** 2012-10-17 10:48**MOT test number** 648381592219**Result** ✗ Failed**Notice** O/s/r tyre has signs of perishing**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

**MOT #3** 2011-10-10 14:54**MOT test number** 668263281222**Result** ✓ Passed**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-10-10 11:13**MOT test number** 386183981469**Result** ✗ Failed**Fail** Offside front brake binding (3.7.B.1)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-11-04 11:21**MOT test number** 673508900390**Result** ✓ Passed**Notice** Both front tyres worn on inner edges



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-20
Last registration	2022-10-12
Complete history	<a href="#">See info</a>



Registration #1	2007-11-20	6 mi
Registration #2	2010-11-04	30.164 mi
Registration #3	2011-10-10	39.994 mi
Registration #4	2011-10-10	39.996 mi
Registration #5	2012-10-17	50.328 mi
Registration #6	2013-10-15	60.965 mi
Registration #7	2014-10-09	64.584 mi
Registration #8	2015-10-12	67.777 mi
Registration #9	2015-10-13	67.777 mi
Registration #10	2016-10-08	71.895 mi
Registration #11	2016-10-08	71.895 mi
Registration #12	2016-10-08	71.895 mi
Registration #13	2016-10-08	71.895 mi
Registration #14	2016-10-08	71.895 mi
Registration #15	2016-10-08	71.895 mi
Registration #16	2016-10-08	71.895 mi
Registration #17	2016-10-08	71.895 mi
Registration #18	2016-10-08	71.895 mi
Registration #19	2016-10-08	71.895 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	946 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	G4HG7M076556