



report date: 2024-03-29

## General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-28
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-12
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	8
Total items failed	5

MOT #12	2024-03-13 11:23
MOT test number	831395448661
Result	✓ Passed
Next expiry date	2025-03-12

MOT #11	2023-02-16 09:32
MOT test number	127241592474
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-02-16 09:32
MOT test number	901302412062
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Front Outline marker lamp not working (4.2.1 (a) (ii))
Pass with rectification	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Offside Front Outline marker lamp not working (4.2.1 (a) (ii))

**MOT #9** 2022-02-17 12:48**MOT test number** 547548905661**Result** ✓ Passed**MOT #8** 2021-06-16 14:42**MOT test number** 466525929330**Result** ✓ Passed**MOT #7** 2020-06-18 13:57**MOT test number** 995194462254**Result** ✓ Passed**MOT #6** 2019-06-21 09:47**MOT test number** 798188597394**Result** ✓ Passed

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #5** 2019-06-20 15:59**MOT test number** 616898239011**Result** ✗ Failed

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #4** 2018-06-12 13:43**MOT test number** 191742478766**Result** ✓ Passed

**MOT #3** 2017-06-16 09:59**MOT test number** 812828519837**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #2** 2016-05-27 12:34**MOT test number** 483712176010**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2015-06-18 10:00**MOT test number** 166339765125**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
12 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	12 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-19
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2012-06-19	29 mi
Registration #2	2015-06-18	36.247 mi
Registration #3	2016-05-27	46.674 mi
Registration #4	2017-06-16	56.587 mi
Registration #5	2018-06-12	66.788 mi
Registration #6	2019-06-20	80.736 mi
Registration #7	2019-06-21	80.736 mi
Registration #8	2019-06-21	80.736 mi
Registration #9	2019-06-21	80.736 mi
Registration #10	2019-06-21	80.736 mi
Registration #11	2019-06-21	80.736 mi
Registration #12	2019-06-21	80.736 mi
Registration #13	2019-06-21	80.736 mi
Registration #14	2019-06-21	80.736 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1133407