



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Grey
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-03-04
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-18
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	21
Total items failed	14

MOT #172024-04-22 17:31

MOT test number607371511827

Result✓ Passed

Next expiry date2025-05-18

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin Both (1.1.13 (a) (ii))

MOT #162024-04-22 08:29

MOT test number218082685048

Result✗ Failed

Fail Nearside Front Tyre has ply or cords exposed Inner edge (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin Both (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

MOT #152023-04-27 15:57

MOT test number143025334616

Result✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))

**MOT #14**

2023-04-27 15:57

MOT test number

368379543329

Result**✗ Failed****Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**MOT #13**

2022-05-19 15:38

MOT test number

375153186702

Result**✓ Passed****MOT #12**

2022-05-16 13:05

MOT test number

345578618779

Result**✗ Failed****Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Offside Headlamp aim too low (4.1.2 (a))**MOT #11**

2021-10-15 08:04

MOT test number

610917119470

Result**✓ Passed****Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2020-10-09 11:19**MOT test number** 133421817224**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2019-10-10 10:03**MOT test number** 380921062423**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-10-11 09:21**MOT test number** 713709732146**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2017-10-18 13:35**MOT test number** 645769432736**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-10-13 13:01**MOT test number** 350920788165**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Offside Steering rack insecure (2.2.B.1a)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Headlamp aim too low (1.8)**MOT #5** 2016-10-14 11:58**MOT test number** 329362380912**Result** ✓ Passed**Advice** Front number plate damaged**MOT #4** 2015-09-25 12:45**MOT test number** 661101036859**Result** ✓ Passed**MOT #3** 2014-06-24 15:51**MOT test number** 278555774112**Result** ✓ Passed



MOT #2	2014-06-24 15:28
MOT test number	177365474141
Result	✗ Failed
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Offside Front Headlamp cleaning device inoperative (1.7.2)
Fail	Nearside Front Headlamp cleaning device inoperative (1.7.2)

MOT #1	2013-08-16 12:13
MOT test number	316428923237
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
18 May 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	18 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DU600DJ
Plate since	2019-03-29
Current registration	DU600DJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-01
Last registration	2024-04-22
Complete history	See info



Registration #1	2010-09-01	27 mi
Registration #2	2013-08-16	20.367 mi
Registration #3	2014-06-24	30.599 mi
Registration #4	2014-06-24	30.599 mi
Registration #5	2015-09-25	51.010 mi
Registration #6	2016-10-14	58.908 mi
Registration #7	2017-10-13	63.864 mi
Registration #8	2017-10-18	63.867 mi
Registration #9	2018-10-11	69.929 mi
Registration #10	2019-10-10	73.793 mi
Registration #11	2019-10-10	73.793 mi
Registration #12	2019-10-10	73.793 mi
Registration #13	2019-10-10	73.793 mi
Registration #14	2019-10-10	73.793 mi
Registration #15	2019-10-10	73.793 mi
Registration #16	2019-10-10	73.793 mi
Registration #17	2019-10-10	73.793 mi
Registration #18	2019-10-10	73.793 mi
Registration #19	2019-10-10	73.793 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1361361