



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 HDI VTR
Colour	Silver
Year of manufacture	2010
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-04
Pictures	5
Listing price	View report



New Stock

Vehicle Awaiting Full Preparation

Full HD photo pack soon

Please call before visiting to check this car is ready to view and test drive

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	25
Total items failed	17

MOT #18 2023-07-31 11:45

MOT test number 460708580501

Result ✓ Passed

Next expiry date 2024-08-10

Advice Nearside Rear Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17 2023-07-31 08:45

MOT test number 422174569059

Result ✗ Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #16**

2022-08-11 11:14

MOT test number

504075761382

Result

✓ Passed

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15**

2022-07-29 07:43

MOT test number

936452563029

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear one (5.3.4 (a) (i))**Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn rear one (5.3.4 (a) (i))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #14**

2021-08-09 13:24

MOT test number

275840323183

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2021-08-06 14:52**MOT test number** 245995851086**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Spare tyre defective**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2021-01-26 12:10**MOT test number** 694006990142**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust slightly deteriorated behind front flexi-pipe**MOT #11** 2020-01-27 11:24**MOT test number** 307899691130**Result** ✓ Passed**MOT #10** 2020-01-27 11:24**MOT test number** 738302320796**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #9** 2019-01-30 11:40**MOT test number** 684289308686**Result** ✓ Passed

**MOT #8** 2019-01-25 10:07**MOT test number** 914299250184**Result** ✗ Failed**Fail** Tailgate cannot be secured in the closed position (6.2.1 (e))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #7** 2018-01-23 13:12**MOT test number** 819044622464**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Front (2.4.G.2)**MOT #6** 2017-01-25 10:53**MOT test number** 297318923792**Result** ✓ Passed**MOT #5** 2016-01-18 15:02**MOT test number** 584555453134**Result** ✓ Passed**Advice** Rear tyres perishing.

**MOT #4** 2016-01-18 11:29**MOT test number** 729526104174**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Rear tyres perishing.**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2015-01-28 12:50**MOT test number** 867518225057**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2014-01-09 11:52**MOT test number** 565129204011**Result** ✓ Passed**MOT #1** 2013-01-29 10:16**MOT test number** 946599623032**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-25
Last registration	2023-07-31
Complete history	See info



Registration #1	2010-01-25	6 mi
Registration #2	2013-01-29	15.221 mi
Registration #3	2014-01-09	20.717 mi
Registration #4	2015-01-28	26.299 mi
Registration #5	2016-01-18	30.263 mi
Registration #6	2016-01-18	30.263 mi
Registration #7	2017-01-25	35.210 mi
Registration #8	2018-01-23	40.386 mi
Registration #9	2019-01-25	46.324 mi
Registration #10	2019-01-30	46.410 mi
Registration #11	2019-01-30	46.410 mi
Registration #12	2019-01-30	46.410 mi
Registration #13	2019-01-30	46.410 mi
Registration #14	2019-01-30	46.410 mi
Registration #15	2019-01-30	46.410 mi
Registration #16	2019-01-30	46.410 mi
Registration #17	2019-01-30	46.410 mi
Registration #18	2019-01-30	46.410 mi
Registration #19	2019-01-30	46.410 mi
Registration #20	2019-01-30	46.410 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1003 kg
Max. allowed weight	1391 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FDBE2555517