



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-03
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	20
Total items failed	14

MOT #14	2023-10-02 08:36
MOT test number	856565243079
Result	✓ Passed
Next expiry date	2024-10-03
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-10-04 12:20
MOT test number	469517065256
Result	✓ Passed

MOT #12	2022-10-04 12:20
MOT test number	813392962711
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11	2021-09-09 15:37
MOT test number	830621349738
Result	✓ Passed

**MOT #10**

2021-09-09 10:53

MOT test number

984787436804

Result**✗ Failed****Fail**

Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Nearside Rear Nail in tyre

Fail

Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9

2020-09-28 17:46

MOT test number

317730995325

Result**✓ Passed****Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #8

2019-09-14 08:23

MOT test number

471282265577

Result**✓ Passed****Advice**

Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-09-29 09:19**MOT test number** 749483576085**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

MOT #6 2017-09-25 06:23**MOT test number** 367308569386**Result** ✓ Passed

- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #5 2016-09-02 13:01**MOT test number** 851188814095**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #4 2016-08-31 15:23**MOT test number** 416853769797**Result** ✗ Failed

- Fail** Nearside Rear Rear wheel bearing rough when rotated (2.6.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #3** 2015-10-02 10:12**MOT test number** 682640180243**Result** ✓ Passed**MOT #2** 2014-11-12 16:19**MOT test number** 807126114381**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2014-11-12 16:19**MOT test number** 116796214371**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
3 October 2024

Tax status		Valid until 1 September
Days left		124
MOT expiry date		3 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FP61WVG
Plate since	2019-03-29
Current registration	 FP61WVG
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-11-22
Last registration	2023-10-02
Complete history	See info



Registration #1	2011-11-22	10 mi
Registration #2	2014-11-12	37.963 mi
Registration #3	2015-10-02	47.866 mi
Registration #4	2016-08-31	59.483 mi
Registration #5	2016-09-02	59.483 mi
Registration #6	2017-09-25	64.024 mi
Registration #7	2018-09-29	78.912 mi
Registration #8	2019-09-14	90.049 mi
Registration #9	2020-09-02	90.049 mi
Registration #10	2020-09-02	90.049 mi
Registration #11	2020-09-02	90.049 mi
Registration #12	2020-09-02	90.049 mi
Registration #13	2020-09-02	90.049 mi
Registration #14	2020-09-02	90.049 mi
Registration #15	2020-09-02	90.049 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1841 mm
Length	4875 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CAY 511109